


AD-A092 092

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/13
NATIONAL DAM SAFETY PROGRAM. GARNERVILLE DAM (INVENTORY NUMBER --E7C(U)
AUG 80 E O'BRIEN DACW51-79-C-0001
NL

UNCLASSIFIED

1 of 2
AD-A
092092



AD A092042

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT. ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
	AD-A092042	
4. TITLE (and Subtitle) Phase I Inspection Report Garnerville Dam Hudson River Basin, Rockland County, New York Inventory No. 744		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) Eugene O'Brien		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Tippetts-Abbott-McCarthy-Stratton 655 Third Avenue New York, NY 10017		8. CONTRACT OR GRANT NUMBER(s) ✓ DACW-51-79-C-0001
11. CONTROLLING OFFICE NAME AND ADDRESS New York State Department of Environmental Conservation 50 Wolf Road Albany, NY 12233		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287		12. REPORT DATE 11 September 1980
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) THIS DOCUMENT IS UNCLASSIFIED. THE INFORMATION CONTAINED HEREIN IS A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.		
18. SUPPLEMENTARY NOTES *Original contains color plates; All DTIC reproductions will be in black and white*		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Hydrology, Structural Stability Granerville Dam Rockland County Minisceongo Hudson River		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Examination of available documents and a visual inspection of the dam and the appurtenant structures did not reveal conditions which constitute an immediate hazard to human life or property.		

LEVEL II

DTIC
ELECTE
NOV 25 1980
C

DDG FILE COPY

Using Corps of Engineers screening criteria, it has been determined that the dam would be overtopped for all storms exceeding approximately 19 percent of Probable Maximum Flood (PMF). The spillway is, therefore, adjudged as "seriously inadequate" and the dam is assessed as unsafe, non-emergency.

The classification of "unsafe" applied to a dam because of a "seriously inadequate spillway" is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening, and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream from the dam.

It is, therefore, recommended that within 3 months of notification to the owner, detailed hydrological hydraulic investigations of the structure should be undertaken to more accurately determine the site specific characteristics of the watershed and their affect upon the overtopping potential of the dam. At the same time further analysis of the structural stability of the overflow and non-overflow section should be performed. The results of these investigations analysis will determine the appropriate remedial measures which will be required to achieve a spillway capacity adequate to discharge the outflow from at least the 1/2 PMF. In the interim, a detailed emergency action plan must be developed and implemented during periods of unusually heavy precipitation. Also, around-the-clock surveillance of the structure must be provided during these periods.

On the basis of Stability Analysis performed during the investigation, the structural stability of the non-overflow section of the dam against overturning was determined to be adequate for all cases except the Extreme Loading: PMF. The structural stability of the non-overflow section of the dam against sliding was determined to be adequate for all cases except Unusual Loading: one-half PMF, and Extreme Loading: PMF.

On the basis of Structural Stability performed during the investigation, the structural stability of the overflow section of the dam against overturning was determined to be adequate for all cases except Normal Loading condition with ice load and Extreme Loading: PMF. The stability of the overflow section of the dam against sliding was determined to be adequate for all cases except Normal Loading condition with ice load, Unusual Loading: one-half PMF, and Extreme Loading: PMF.

The following remedial measures must be completed within 1 year:

- Backfill the low saddle in the right abutment to an elevation equal to that of the top of the dam.
- Monitor the seepage of the downstream of the right abutment and through the masonry on the downstream face of the dam at bi-weekly intervals with aid of weirs. In addition determine the source of the seepage in the right abutment.
- Remove all trees on the backfill at the upstream face of the dam. Provide a program of periodic cutting and brushing of the backfill.
- Remove and haul away debris from the spillway crest.
- Remove and haul away debris and boulders from the tailrace area of the spillway immediately downstream of the dam.
- Provide a program of periodic inspection and maintenance of the dam and appurtenances, including yearly operation and lubrication of the reservoir drain system. Document this information for future reference. The emergency action plan described in section 7.1d should be maintained and updated periodically during the life of the structure.

8

HUDSON RIVER BASIN

GARNERVILLE DAM

**ROCKLAND COUNTY, NEW YORK
INVENTORY NO. N.Y. 744**

**PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**

DTIC
SELECTED
NOV 25 1980
C



NEW YORK DISTRICT CORPS OF ENGINEERS

AUGUST 1980

**APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED
CONTRACT NO. DACW-51-79-C0001**

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

(10) Eugene/Strien

(8)

(6) **HUDSON RIVER BASIN**
National Dam Safety Program
GARNERVILLE DAM

ROCKLAND COUNTY, NEW YORK
(INVENTORY ^{N.Y.C.} ~~NO~~ N.Y. 744)
Hudson River Basin
Rockland County, New York.
PHASE I INSPECTION REPORT,
NATIONAL DAM SAFETY PROGRAM

(15) DACW51-79-C-0001

DTIC
ECTE
NOV 25 1980



(12) 116

NEW YORK DISTRICT CORPS OF ENGINEERS

(11) AUGUST 1980

393970

AM

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C., 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Recommendation For	✓	□	□	□
TIC & I				
TIC & I				
Reviewed				
Utilization				
Y				
Availability				
st				
23				
A				
CP				

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
GARNERVILLE DAM
I.D. NO. N.Y. 744
DEC No. 337 B
HUDSON RIVER BASIN
ROCKLAND COUNTY, NEW YORK

	<u>Page</u>
- ASSESSMENT	
- OVERVIEW PHOTOGRAPH	
1 PROJECT INFORMATION	1
1.1 GENERAL	1
a. Authority	1
b. Purpose of Inspection	1
1.2 DESCRIPTION OF THE PROJECT	1
a. Description of the Dam and Appurtenant Structures	1
b. Location	2
c. Size Classification	2
d. Hazard Classification	2
e. Ownership	2
f. Purpose of Dam	2
g. Design and Construction History	2
h. Normal Operating Procedure	2
1.3 PERTINENT DATA	3
a. Drainage Area	3
b. Discharge at Dam Site	3
c. Elevation	3
d. Reservoir	3
e. Storage	3
f. Dam	3
g. Spillway	3
h. Reservoir Drain and Pipeline	3
2 ENGINEERING DATA	5
2.1 GEOLOGY	5
a. Geology	5
2.2 SUBSURFACE INVESTIGATIONS	5
2.3 DAM AND APPURTENANT STRUCTURES	5
2.4 CONSTRUCTION RECORDS	5
2.5 OPERATION RECORD	5
2.6 EVALUATION OF DATA	5

	<u>Page</u>
3 VISUAL INSPECTION	6
3.1 FINDINGS	6
a. General	6
b. Main Dam	6
c. Spillway and Tailrace	6
d. Reservoir Drain and Pipeline	7
e. Reservoir Area	7
3.2 EVALUATION OF OBSERVATIONS	7
4 OPERATION AND MAINTENANCE PROCEDURES	8
4.1 PROCEDURES	8
4.2 MAINTENANCE OF DAM	8
4.3 WARNING SYSTEM IN EFFECT	8
4.4 EVALUATION	8
5 HYDROLOGIC/HYDRAULIC	9
5.1 DRAINAGE BASIN CHARACTERISTICS	9
5.2 ANALYSIS CRITERIA	9
5.3 SPILLWAY CAPACITY	9
5.4 RESERVOIR CAPACITY	9
5.5 FLOODS OF RECORD	9
5.6 OVERTOPPING POTENTIAL	10
5.7 EVALUATION	10
6 STRUCTURAL STABILITY	11
6.1 EVALUATION OF STRUCTURAL STABILITY	11
a. Visual Observations	11
b. Design and Construction Data	11
c. Stability Analysis	11
d. Operation Records	12
e. Post Construction Changes	13
f. Seismic Stability	13
7 ASSESSMENT/RECOMMENDATIONS	14
7.1 ASSESSMENT	14
a. Safety	14

		<u>Page</u>
b.	Adequacy of Information	15
c.	Need for Additional Investigations	15
d.	Urgency	15
7.2	RECOMMENDED MEASURES	15

APPENDIX

- A. DRAWINGS
 - 1. Plan and Section
 - 2. Vicinity Map
 - 3. Topographic and Drainage Basin Map
- B. PHOTOGRAPHS
- C. VISUAL INSPECTION CHECKLIST
- D. HYDRAULIC DATA AND COMPUTATION
- E. STABILITY ANALYSIS
- F. REFERENCES

PHASE I REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Garnerville Dam (I.D. No. 744)
State Located: New York
County Located: Rockland
Stream: Minisceongo
Basin: Hudson River
Date of Inspection: April 24, 1980

ASSESSMENT

Examination of available documents and a visual inspection of the dam and the appurtenant structures did not reveal conditions which constitute an immediate hazard to human life or property.

Using Corps of Engineers screening criteria, it has been determined that the dam would be overtopped for all storms exceeding approximately 19 percent of Probable Maximum Flood (PMF). The spillway is, therefore, adjudged as "seriously inadequate" and the dam is assessed as unsafe, non-emergency.

The classification of "unsafe" applied to a dam because of a "seriously inadequate spillway" is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening, and preliminary computations, there appears to be a serious deficiency in spillway capacity so that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream from the dam.

It is, therefore, recommended that within 3 months of notification to the owner, detailed hydrological hydraulic investigations of the structure should be undertaken to more accurately determine the site specific characteristics of the watershed and their affect upon the overtopping potential of the dam. At the

same time further analysis of the structural stability of the overflow and non-overflow section should be performed. The results of these investigations analysis will determine the appropriate remedial measures which will be required to achieve a spillway capacity adequate to discharge the outflow from at least the 1/2 PMF. In the interim, a detailed emergency action plan must be developed and implemented during periods of unusually heavy precipitation. Also, around-the-clock surveillance of the structure must be provided during these periods.

On the basis of Stability Analysis performed during the investigation, the structural stability of the non-overflow section of the dam against overturning was determined to be adequate for all cases except the Extreme Loading: PMF. The structural stability of the non-overflow section of the dam against sliding was determined to be adequate for all cases except Unusual Loading: one-half PMF, and Extreme Loading: PMF.

On the basis of Structural Stability performed during the investigation, the structural stability of the overflow section of the dam against overturning was determined to be adequate for all cases except Normal Loading condition with ice load and Extreme Loading: PMF. The stability of the overflow section of the dam against sliding was determined to be adequate for all cases except Normal Loading condition with ice load, Unusual Loading: one-half PMF, and Extreme Loading: PMF.

The following remedial measures must be completed within 1 year:

- Backfill the low saddle in the right abutment to an elevation equal to that of the top of the dam.
- Monitor the seepage of the downstream of the right abutment and through the masonry on the downstream face of the dam at bi-weekly intervals with aid of weirs. In addition determine the source of the seepage in the right abutment.
- Remove all trees on the backfill at the upstream face of the dam. Provide a program of periodic cutting and brushing of the backfill.
- Remove and haul away debris from the spillway crest.
- Remove and haul away debris and boulders from the tailrace area of the spillway immediately downstream of the dam.

same time further analysis of the structural stability of the overflow and non-overflow section should be performed. The results of these investigations analysis will determine the appropriate remedial measures which will be required to achieve a spillway capacity adequate to discharge the outflow from at least the 1/2 PMF. In the interim, a detailed emergency action plan must be developed and implemented during periods of unusually heavy precipitation. Also, around-the-clock surveillance of the structure must be provided during these periods.


On the basis of Stability Analysis performed during the investigation, the structural stability of the non-overflow section of the dam against overturning was determined to be adequate for all cases except the Extreme Loading: PMF. The structural stability of the non-overflow section of the dam against sliding was determined to be adequate for all cases except Unusual Loading: one-half PMF, and Extreme Loading: PMF.

On the basis of Structural Stability performed during the investigation, the structural stability of the overflow section of the dam against overturning was determined to be adequate for all cases except Normal Loading condition with ice load and Extreme Loading: PMF. The stability of the overflow section of the dam against sliding was determined to be adequate for all cases except Normal Loading condition with ice load, Unusual Loading: one-half PMF, and Extreme Loading: PMF.

The following remedial measures must be completed within 1 year:


- Backfill the low saddle in the right abutment to an elevation equal to that of the top of the dam.
- Monitor the seepage of the downstream of the right abutment and through the masonry on the downstream face of the dam at bi-weekly intervals with aid of weirs. In addition determine the source of the seepage in the right abutment.
- Remove all trees on the backfill at the upstream face of the dam. Provide a program of periodic cutting and brushing of the backfill.
- Remove and haul away debris from the spillway crest.
- Remove and haul away debris and boulders from the tailrace area of the spillway immediately downstream of the dam.

- Provide a program of periodic inspection and maintenance of the dam and appurtenances, including yearly operation and lubrication of the reservoir drain system. Document this information for future reference. The emergency action plan described in section 7.1d should be maintained and updated periodically during the life of the structure.



Eugene O'Brien, P.E.
New York, No. 29823

Approved By:



W. M. Smith, Jr.
New York District Engineer

Date:

11 Sep 80



1. GENERAL OVERVIEW OF DAM

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
GARNERVILLE DAM
I. D. NO. N.Y. 744
DEC No. 337 B
HUDSON RIVER BASIN
ROCKLAND COUNTY, NEW YORK

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase I inspection reported herein was authorized by the State of New York, Department of Environmental Conservation, by letter dated 7 January 1980, in fulfillment of the requirements of the National Dam Inspection Act, Public Law 92-367, 8 August 1972.

b. Purpose of Inspection

This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, to determine if these deficiencies constitute hazards to life and property, and to recommend remedial measures where required.

1.2 DESCRIPTION OF THE PROJECT

a. Description of the Dam and Appurtenant Structure

The Garnerville Dam is composed of a 330 foot long masonry structure that includes a 69 foot long overflow section, serving as a spillway. There are two reservoir drains, one 30-inches in diameter and one 8-inch, both are controlled by gate valves.

The crest of the embankment is 13 feet wide and the upstream and downstream slopes are 1H to 4.5V. The maximum height of the structure above the stream is 28 feet. The spillway opening, which is 6.9 feet deep, is located slightly to the left of the center of the dam and has a slightly rounded overflow crest. The 30-inch reservoir drain passes beneath the dam just to the left of the left side of the spillway and exists about 10 feet downstream of the toe. It is controlled by a gate valve located about 6 feet upstream of the dam. The 8-inch low level outlet passes slightly to the left of the 30-inch outlet and continues downstream to the town of Garnerville. It is controlled by a valve located near the toe of the dam.

The upstream slope of the masonry structure is covered with impervious clay fill and stone paving.

It is also reported and observations further indicated that the entire reservoir is lined with an impervious clay layer covered by cobblestone.

b. Location

Garnerville Dam is located on Minisceongo Creek, a tributary of the Hudson River in West Haverstraw, New York about 1-1/2 miles west of Garnerville, New York, approximately 0.75 miles north of State Route 202. The dam is in a sparsely populated residential area and directly upstream of the village of Garnerville.

c. Size Classification

The dam is 29 feet high and has a reservoir (29 feet high) with a storage capacity of 198 acre-feet and, therefore, is classified as a small dam.

d. Hazard Classification

The dam is in the "high" hazard potential category because of the close proximity of the dam to residences and its location within the town of Garnerville.

e. Ownership

Garnerville Dam is owned by the Garnerville Holding Company, 55 Railroad Avenue, Garnerville, New York 10923, Tel. (914) 947-1155, and operation and maintenance is carried out by the owner. The person to contact at the company is Mr. David Lipman.

f. Purpose of Dam

The dam was originally constructed as the uppermost of a series of dams to provide water for an industrial facility, located in Garnerville. The water is for the most part no longer used for this purpose with the exception of the 8-inch outlet which is still utilized at the company plant. Otherwise, the dam is used for recreational purpose.

g. Design and Construction History

There are no design drawings or records of the construction of the dam. The construction of the dam was completed in 1875.

h. Normal Operating Procedure

Water is continuously released from the reservoir through the 8-inch pipeline; and over the spillway through most of the year depending on the inflow. The 30-inch reservoir drain is operated periodically to check its operability and as required to lower the reservoir below spillway crest.

1.3

PERTINENT DATA

- a. Drainage Area (sq. mile) 17.5
- b. Discharge at Dam Site (CFS)
 Ungated spillway at maximum pool 3,890
 Maximum capacity of low level outlets 150
 Total discharge, Maxi. Pool (El. 216.9) 4,040
- c. Elevation (feet above MSL USGS Datum)
 Top of Dam 216.9
 Maximum Design Pool 210.0
 Spillway Crest 210.0
 Invert low level outlets 188.0
- d. Reservoir
 Length of Maximum Pool (feet) 1,150
 Length of Shoreline at Spillway Crest (feet) 3,200
 Surface Area Acre 10.2
- e. Storage (acre-feet)
 Reservoir at Spillway Crest 100.0
 Reservoir at Maximum Pool (Top of Dam) 198.0
- f. Dam
 Type Masonry Gravity Dam
 Length (feet) 328.5
 Upstream Slope 1H to 4.5V
 Downstream Slope 1H to 4.5V -
 (Covered with fill and
 stone paving to \pm
 30° slope)
 Crest Elevation 216.9
 Crest Width (feet) 13
 Grout Curtain None
- g. Spillway
 Type Broadcrested overflow
 section of dam
 Length (feet) 69 feet
 Crest Elevation (MSL) 210
 Upstream Channel None
 Downstream Channel 100 feet wide (boulders
 and debris in stream)
- h. Reservoir Drain and Pipeline

Upstream: A dual intake structure is located 11.5 feet to the left of the overflow section, included is a gate valve for the 30-inch pipe, and a screen type structure. It was not possible to ascertain exact invert levels of intakes.

Downstream: The outlet for 30-inch cast iron pipe is located in a channel about 10 feet from downstream toe just left of overflow section. Control for the 8-inch pipe is near the toe of the dam 85-feet left from the center of the overflow section.

SECTION 2 - ENGINEERING DATA

2.1 GEOLOGY

a. Geology

The records of the owner contain no data on site geology. However, there is data available in the literature on the general geology of the area. The rock in the area is the Brunswick Formation of the Newark Group of the upper Triassic. Generally, the rocks of this formation are sandstone, red shale conglomerate and limestone. No outcrops existed at the dam site to confirm the existence of this type of rock.

2.2 SUBSURFACE INVESTIGATIONS

No subsurface investigation could be located for the dam. However, the General Soil Map of New York State prepared by the Cornell University Experiment Station (1968) indicates that the surficial soils around Garnerville Dam are of the Rockaway-Chatfield Association. This association is dominated by well drained, moderately coarse textured sandy loams and loams on glacial till derived from granitic rocks.

2.3 DAM AND APPURTENANT STRUCTURES

There are virtually no records or drawings with regard to the original construction of the dam or low level outlet structures. There are a few sketches of the outlet works in the records of the owner.

2.4 CONSTRUCTION RECORDS

No information has been located in relation to the construction of the project. The completion is assumed to be 1875 from a Marble Plaque located on the dam. The name of the contractor is unknown.

2.5 OPERATION RECORD

In recent years there has been no regular operation of the dam and no records were kept of the reservoir operation. The dam is inspected on occasion by the maintenance staff of the owner but no regular maintenance is carried out, and no systematic monitoring of the performance of the dam is in effect.

2.6 EVALUATION OF DATA

There is little data available about the design or construction of the dam. There are reportedly some drawings with regard to the construction of the outlet works available in the records of the owner, but these, although reported, were not made available to us. Although the data is not adequate for an in-depth evaluation, estimates, field observations, measurements and discussions regarding past history and performance of the dam, supports sufficient data for Phase I evaluation.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General

The visual inspection of Garnerville Dam was made on April 24, 1980. The weather was fair and the temperature was 60° to 65°F. The reservoir had been lowered about 1 to 2 feet to allow inspection of the spillway crest and downstream face.

b. Main Dam

The main dam which was completed in 1875 shows no signs of major distress or structural problems. The vertical and horizontal alignment of the crest appears to be unchanged. There are no major cracks in the masonry joints on the dam or spillway sections. However, the following adverse conditions were noted.

(1) There is minor seepage through small cracks in the masonry near the toe of the dam on the left non-overflow section.

(2) There is a low saddle on the right abutment which appears to be the result of construction activities in the area. Seepage of about 5 gpm emanates from the ground about 1,000 feet directly downstream from this point. There is no indication of fines being washed.

(3) There is a large amount of tree growth on the right non-overflow section of the dam immediately upstream of the crest of the dam.

(4) There is a zone of ice damage in the masonry wherever it is exposed to the reservoir.

c. Spillway and Tailrace

The downstream face at the spillway appears to be in good condition. It was difficult to observe the condition of the crest of the spillway due to the remains of the flashboard structure, which was constructed to increase the storage capacity of the reservoir. At the time of the flashboard construction, a large stair step like overflow crib structure was constructed downstream of the spillway. Both structures have since been demolished by a flood (reportedly in 1956). The spillway crest has the general appearance, therefore, of being in much poorer condition. However, between the remains of the flashboards the crest appears to be in good condition.

The tailrace channel of the spillway is full of debris from the flashboard structure, overflow crib structure, and boulders. The channel is also choked intermittently for a substantial distance downstream with fallen trees and the abutments of several old bridges.

d. Reservoir Drain and Pipeline

The regulating gates for the 30-inch reservoir drain and the 8-inch pipeline are in good operating condition and appear to be well maintained.

e. Reservoir Area

There are neither slides, rockfalls, sloughing or other signs of instability in the vicinity of the dam. There are, however, small earth slides at the eastern end of the reservoir 0.5 mile from dam. The slides are likely the result of vandals breaking apart a number of stone retaining walls built around the dam. These do not appear to present a hazardous condition. There were no objectionable amounts of floating debris in the reservoir.

3.2 EVALUATION OF OBSERVATIONS

Although deficiencies were observed there is no indication that the dam is in imminent danger. A number of the deficiencies observed in the previous paragraphs are minor and should be corrected by the maintenance forces. Other conditions described above, however, represent conditions which may have potential for further deterioration for this reason, these conditions need to be further investigated.

Significant conditions which were observed which require immediate investigation to determine the extent of corrective action necessary to determine the stability of the dam and appurtenances. The following is a summary of the problem areas encountered, in order of importance, with the appropriate recommended action:

1. Backfill the low saddle in the right abutment to an elevation equal to that of the top of the dam.
2. Monitor the seepage at the downstream of the right abutment and through the masonry on the downstream face of the dam at bi-weekly intervals with aid of weirs. In addition determine the source of the seepage in the right abutment.
3. Remove all trees on backfill at the upstream face of the dam.
4. Remove and haul away debris from the spillway crest.
5. Remove and haul away debris and boulders from the tailrace area for the spillway immediately downstream of the dam.
6. Provide a program of periodic inspection and maintenance of the dam and appurtenances, including yearly operation and lubrication of the reservoir drain system. Document this information for future reference. The emergency action plan described in section 7.1d should be maintained and updated periodically during the life of the structure.

SECTION 4 - OPERATION AND MAINTENANCE PROCEDURES

4.1 PROCEDURES

The Garnerville reservoir discharges continuously through the 8-inch cast iron pipe and over the spillway throughout most of the year. Flow through the 8-inch pipeline goes directly to the manufacturing facility downstream and could be controlled through a valve at the downstream toe of the dam. Flow over the spillway is uncontrolled above spillway crest elevation 210. The 30-inch outlet is opened to lower the reservoir or check the operating mechanism.

4.2 MAINTENANCE OF DAM

There is no regular maintenance schedule for the dam. The dam is checked periodically by the maintenance staff of the owner and in particular the operating mechanisms are checked. Repair programs have been carried out, as required in the past, particularly in attempts to repair seepage in the masonry of the dam. The reservoir drain and pipeline are in good operating condition and appear to be maintained regularly. It is reported that due to vandalism the operation of the controls for the reservoir drains are checked regularly. The gate valves for the reservoir drain and pipeline are in good operating condition.

4.3 WARNING SYSTEM IN EFFECT

There are no warning systems in effect or in preparation.

4.4. EVALUATION

The overall maintenance of the Garnerville Dam is considered to be less than inadequate in the following area.

- (a) Control of vegetation and tree growth on upstream backfill.
- (b) Maintenance of the spillway crest and downstream tailrace area.
- (c) No formal operation and maintenance manuals exist in the project.

SECTION 5 - HYDROLOGIC/HYDRAULIC

5.1 DRAINAGE BASIN CHARACTERISTICS

Garnerville Dam is located on Minisceongo Creek in West Haverstraw, Rockland County, New York. The watershed contributing to the reservoir is 17.5 square miles and is drained by Minisceongo Creek and its tributary, South Branch. Landcover varies from thickly wooded slopes through orchards, pastures, urban areas and several ponds and swamps. The longest watercourse is approximately 9.5 miles and falls over 1,000 feet to the normal lake elevation 210. The tributary, South Branch, flows northward and enters Minisceongo Creek about 2.4 miles upstream of the dam, falling from an elevation of 675 feet at its southern divide to about 370 feet at its confluence, a distance of approximately 5.7 miles.

5.2 ANALYSIS CRITERIA

The analysis of the Garnerville Dam was performed using the Corps of Engineers HEC-1 computer program¹/. Because of the number of tributaries and the shape of the watershed contributing to the reservoir, it was necessary to divide the basin into three subareas. Snyder synthetic unit hydrographs were derived for each subarea and the reservoir inflow was simulated from this complex watershed. In accordance with the recommended guidelines of the Corps of Engineers⁷/, the adequacy of the spillway was analyzed using the Probable Maximum Flood (PMF) and one-half the PMF.

5.3 SPILLWAY CAPACITY

The principal spillway of Garnerville Dam is centrally located, 69 feet in length and 6.9 feet in depth. The crest is triangular in shape and is estimated to be at El 210. The computed maximum spillway discharge with the lake surface at El 216.9 is 3,890 cfs.

5.4 RESERVOIR CAPACITY

There was no data available on the normal capacity of Garnerville reservoir. However, for the purpose of this analysis, it has been estimated that normal capacity is 100 acre-feet, surcharge storage between spillway crest (El 210) and top of dam (El 216.9) is 98 acre-feet, which is equivalent to 0.1 inches of runoff over the entire basin. Maximum or total capacity of the reservoir is 198+ acre-feet.

5.5 FLOODS OF RECORD

There are no available records of the floods or maximum reservoir elevations. Maximum discharge at the Minisceongo Creek gage at Thiells (1959-1963) was 747 cfs on August 10, 1960.

5.6 OVERTOPPING POTENTIAL

The potential of the dam being overtopped was investigated on the basis of the spillway capacity and the available surcharge storage to meet the selected design flood inflows. The Probable Maximum Precipitation (PMP) for the Garnerville Dam area was obtained from Hydrometeorological Report No. 334/. The 24-hour index rainfall for each subarea was 21.9 inches. The initial rainfall loss for subareas A and B was estimated to be 2.0 inches in order to reflect the available surface storage, while subarea C with little basin storage had an initial loss of 1.0 inch. The constant loss for the entire basin was assumed to be 0.1 inches per hour. The combination of the hydrographs resulted in a peak inflow of 20,120 cfs. (1,000 CSM).

The PMF routed through the reservoir resulted in a peak outflow of 20,080 cfs and a corresponding water surface elevation of 222.87, 5.97 feet about the top of the dam. One-half the PMF overtops the dam by 2.84 feet with a peak discharge of 10,000 cfs. The spillway is capable of passing 19.4% of the PMF without overtopping the dam.

5.7 EVALUATION

The Garnerville Dam does not have sufficient spillway capacity to pass either the PMF or one-half the PMF. As a result of the spillways insufficient capacity and the condition as previously reported, which exists on the right abutment, the dam is assessed as seriously inadequate.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

Visual observations did not indicate existing problems with the structure of the dams. The observed seepage on the downstream left wing of the dam is not considered to represent an unstable or otherwise dangerous condition. A potential stability problem does exist, however, because of the low point in the right abutment and the resulting higher potential for erosion.

b. Design and Construction Data

There exists no design computation or other data regarding the structural stability of the dam and the spillway. There are no documents or drawings showing the as-built section or details of the dam.

c. Stability Analysis

Since there are no contract drawings or documents available showing the full geometry or details of the dam, spillway, and foundation condition.

The primary source of structural and subsurface information used in stability analysis were: geometry observed and measures during the inspection visit and sketches supplied by the state from earlier inspections.

The following tables show the results of the structural stability analysis for spillway and non-overflow sections. The computations of analysis are given in Appendix E.

	<u>Non-Overflow Section</u>	<u>Overturning</u>	<u>Sliding Stability</u>
I)	Normal Loading Condition with Reservoir level at Spillway Crest; no ice load	Inside Middle third	1.92
II)	Normal Loading Condition with Reservoir level at Spillway Crest; with ice load	Inside Middle third	1.64
III)	Unusual Loading: One-half PMF, Water overtopping Dam by 2.84 feet	Inside Middle half	1.03
IV)	Extreme Loading: PMF, Water overtopping the Dam by 5.97 feet	Outside Middle half	0.95
V)	Unusual Loading: Reservoir level at Spillway Crest; 0.05 g earthquake force	Inside Middle half	1.51

	<u>Spillway</u>	<u>Overturning</u>	<u>Sliding Capacity</u>
I)	Normal Loading Condition with Reservoir level at Spillway Crest; no ice load	Inside Middle third	1.53
II)	Normal Loading Condition with Reservoir level at Spillway Crest; with ice load	Outside Middle third	1.3
III)	Unusual Loading: One-half PMF, Water overtopping Dam by 2.84 feet	Inside Middle half	0.90
IV)	Extreme Loading: PMF, Water overtopping the Dam by 5.97 feet	Outside Middle half	0.78
V)	Unusual Loading: Reservoir level at Spillway Crest; 0.05 g earthquake force	Inside Middle half	1.28

On the basis of Stability Analysis performed during the investigation, the structural stability of the non-overflow section of the dam against overturning was determined to be adequate for all cases except the Extreme Loading: PMF. The structural stability of the non-overflow section of the dam against the sliding was determined to be adequate for all cases except Unusual Loading: one-half PMF, and Extreme Loading: PMF.

On the basis of Structural Stability performed during the investigation, the structural stability of the overflow section of the dam against overturning was determined to be adequate for all cases except Normal Loading condition with ice load and Extreme Loading: PMF. The stability of the overflow section of the dam against sliding was determined to be adequate for all cases except Normal Loading condition with ice load, Unusual Loading: one-half PMF, and Extreme Loading: PMF.

Since exact geometry, foundation conditions, upstream backfill characteristics and extent, as well as the extent and magnitude of the uplift pressure are unknown, it is therefore, recommended that with the spillway adequacy studies a more detailed structural stability analysis be performed. Field investigations, should be done to obtain more information regarding the extent and characteristics of the backfill and foundation materials; as well as the quality and condition of the non-exposed masonry of the structure. Based on the results of the analysis, modification of the dam should be recommended as required.

d. Operation Records

There are no records of the regulating gates operations. No major operational problems, which would affect the stability of the dam were reported.

e. Post Construction Changes

Several post construction changes have been carried out on or near the dam which would have an affect on the stability of the dam. The flashboard structure has been constructed across the spillway to raise the reservoir level and, therefore, increase the normal hydrostatic load, but this structure was destroyed during a flood and never rebuilt. A second post construction change which still poses a potential stability problem is the addition of runoff drain to the reservoir near the right abutment. Observations indicate that a low point which exists on the abutment is probably a result of this construction. This creates an area of greater erosion potential.

f. Seismic Stability

The dam is located in Zone 2, therefore, a stability analysis was carried out using a normal reservoir loading (water level at spillway crest) and a 0.05g earthquake factor with Zangers method. The results of this analysis showed the dam to be safe under both overturning and sliding.

SECTION 7 - ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

a. Safety

Examination of the available documents and visual inspections of the Garnerville Dam and appurtenant structures did not reveal conditions which constitute a hazard to human life or property.

Using the Corps of Engineers Screening Criteria for review of spillway adequacy, it has been determined that the dam would be overtopped for all storms exceeding approximately 19.4 percent of the PMF. The overtopping of the dam could cause erosion of the right abutment and near the toe of the dam. This could result in possible instability due to undermining leading to dam failure and thus increasing the hazard to loss of life downstream. The spillway is, therefore, adjudged as "seriously inadequate" and the dam is assessed as unsafe, non-emergency.

The classification of "unsafe" applied to a dam because of a "seriously inadequate" spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency in spillway computations, that if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream from the dam.

On the basis of Stability Analysis performed during the investigation, the structural stability of the non-overflow section of the dam against overturning was determined to be adequate for all cases except the Extreme Loading: PMF. The structural stability of the non-overflow section of the dam against sliding was determined to be adequate for all cases except Unusual Loading: one-half PMF, and Extreme Loading: PMF.

On the basis of Structural Stability performed during the investigation, the structural stability of the overflow section of the dam against overturning was determined to be adequate for all cases except Normal Loading condition with ice load and Extreme Loading: PMF. The stability of the overflow section of the dam against sliding was determined to be adequate for all cases except Normal Loading condition with ice load, Unusual Loading: one-half PMF, and Extreme Loading: PMF.

A more detailed structural stability analysis is required. Field investigations are required to obtain more information regarding the extent and magnitude of uplift pressures under the base of the dam and spillway, quality of the masonry and concrete and the extent and characteristics of the backfill and foundation materials. This information should then be incorporated into a detailed structural stability evaluation.

b. Adequacy of Information

The information and data available were adequate for performance of this investigation.

c. Need for Additional Investigations

Since the spillway is considered to be "seriously inadequate", additional hydrologic/hydraulic investigations are required to more accurately determine the site specific characteristics of the watershed. After the in-depth hydrologic/hydraulic investigations have been completed, remedial measures must be initiated to provide spillway capacity sufficient to discharge the outflow from the 1/2 PMF event. In addition, an investigation of the structural stability of the spillway and non-overflow portions of the dam are required.

d. Urgency

The additional hydrologic/hydraulic investigations and the stability investigation which are required must be initiated within 3 months from the date of notification. Within 1 year of notification, remedial measures as a result of these investigations must be initiated, with completion of these measures during the following year. In the interim, develop an emergency action plan for the notification of downstream residents and proper governmental authorities in the event of overtopping and provide round-the-clock surveillance of the dam during periods of extreme run-off. The other problem areas listed below must be corrected within 1 year from notification.

7.2 RECOMMENDED MEASURES


The following are the recommended measures.


1. Backfill the low saddle in the right abutment to an elevation equal to that of the top of the dam.
2. Monitor the seepages at the downstream of the right abutment and through the masonry on the downstream face of the dam at bi-weekly intervals with aid of weirs. In addition, determine the source of the seepage in the right abutment.
3. Remove all trees on the backfill at the upstream face of the dam. Provide a program of periodic cutting and brushing of the backfill.
4. Remove and haul away debris from the spillway crest.
5. Remove and haul away debris and boulders from the tailrace area for the spillway immediately downstream of the dam.

6. Provide a program of periodic inspection and maintenance of the dam and appurtenances, including yearly operation and lubrication of the reservoir drain system. Document this information for future reference. The emergency action plan described in section 7.1d should be maintained and updated periodically during the life of the structure.

DRAWINGS

APPENDIX A





SCALE: 1 inch = 11.2 Miles


VICINITY MAP

SECTION OF THE HILLOCK

THIELLS QUAD

75 MINUTE BLANKS (1:50,000) MAP
Revised 1964

DRAINAGE BASIN



PHOTOGRAPHS

APPENDIX B



2. VIEW OF UPSTREAM FACE OF DAM.



3. VIEW OF DOWNSTREAM CHANNEL.




4. VIEW OF SPILLWAY AND CREST OF RIGHT NON-OVER FLOW SECTION OF DAM. NOTE: CONDITION OF BOARDS, VEGETATION ON UPSTREAM FACE.



5. VIEW LOOKING TOWARDS LEFT NON-OVER FLOW SECTION OF DAM. NOTE: UPSTREAM VEGETATION, CONTROL FOR RESERVOIR DRAIN, DETERIORATION OF CONCRETE DUE TO FROST ACTION.



6. VIEW OF DOWNSTREAM OF RESERVOIR
DRAIN.



7. VIEW OF OPERATING MECHANISM
FOR RESERVOIR DRAIN




8. VIEW OF CONTROL VALVE FOR 8-INCH WATER SUPPLY PIPE.



9. VIEW OF SEEPAGE ON DOWNSTREAM FACE OF LEFT NON-OVERFLOW SECTION OF DAM.



10. VIEW OF DEPRESSION IN RIGHT ABUTMENT IMMEDIATELY
ADJACENT TO DAM (LOOKING UPSTREAM) .



11. VIEW OF SEEPAGE DOWNSTREAM OF
RIGHT ABUTMENT DEPRESSION.

VISUAL INSPECTION CHECKLIST

APPENDIX C

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam GARNERVILLE DAM

Fed. I.D. # NY 744 DEC Dam No. 196B-337B

River Basin Lower Hudson

Location: Town Garnerville County Rockland

Stream Name Minisceongo Creek

Tributary of Hudson River

Latitude (N) 41° 12' Longitude (W) 74° 00'

Type of Dam Masonry - Gravity

Hazard Category High

Date(s) of Inspection April 24, 1980

Weather Conditions Fair 60°-65° F

Reservoir Level at Time of Inspection El. 210. (During inspection lowered 1 to 2 feet.)

b. Inspection Personnel Kalman Szalay - Principal Geotechnical Engr
Joseph Fiteni, Jr. - Geotechnical Engr

c. Persons Contacted (Including Address & Phone No.) MR William Daker
GARNERVILLE HOLDING COMPANY, 55 Railroad Ave, GARNERVILLE
NY 10942 (914) 947-1155. MR DAVID LIPMAN
Same as above

d. History:

Date Constructed 1875 Date(s) Reconstructed _____

Designer Not Known

Constructed By Not Known

Owner GARNERVILLE Holding Company

2) Embankment

NONE

a. Characteristics

- (1) Embankment Material NA
- (2) Cutoff Type NA
- (3) Impervious Core NA
- (4) Internal Drainage System NA
- (5) Miscellaneous NA

b. Crest

- (1) Vertical Alignment NA
- (2) Horizontal Alignment NA
- (3) Surface Cracks NA
- (4) Miscellaneous NA

c. Upstream Slope

- (1) Slope (Estimate) (V:H) _____
- (2) Undesirable Growth or Debris, Animal Burrows _____
- (3) Sloughing, Subsidence or Depressions _____

(4) Slope Protection _____

(5) Surface Cracks or Movement at Toe _____

d. Downstream Slope

(1) Slope (Estimate - V:H) _____

(2) Undesirable Growth or Debris, Animal Burrows _____

(3) Sloughing, Subsidence or Depressions _____

(4) Surface Cracks or Movement at Toe _____

(5) Seepage _____

(6) External Drainage System (Ditches, Trenches; Blanket) _____

(7) Condition Around Outlet Structure _____

(8) Seepage Beyond Toe _____

e. Abutments - Embankment Contact

(1) Erosion at Contact _____

(2) Seepage Along Contact _____

3) Drainage System

a. Description of System None in existence

b. Condition of System _____

c. Discharge from Drainage System _____

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs, Piezometers, Etc.) None

5) Reservoir

- a. Slopes Generally Stable - Some retaining walls in place
- b. Sedimentation NO EVIDENCE OF EXCESSIVE SEDIMENTATION OBSERVED; NO FLOATING DEBRIS
- c. Unusual Conditions Which Affect Dam None

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) Several Highway Bridge - , Dense Building - Homes AND Businesses
- b. Seepage, Unusual Growth Through Face of Dam and also ~300 feet D/s on left abutment
- c. Evidence of Movement Beyond Toe of Dam None
- d. Condition of Downstream Channel Some blockage by Trees and remains of old Railroad bridges

7) Spillway(s) (Including Discharge Conveyance Channel)

- Over flow section in center portion of Dam
- a. General Attempts have been made at various times to modify or repair the spillway. The result is that the original spillway has been covered by concrete and wood - both of which have now deteriorated
- b. Condition of Service Spillway Difficult to judge due to remnants of previous repairs.

c. Condition of Auxiliary Spillway None

d. Condition of Discharge Conveyance Channel None

8) Reservoir Drain/Outlet

Type: Pipe 30" and 8" Conduit _____ Other _____

Material: Concrete _____ Metal Cast Iron Other _____

Size: 30" and 8" Length 30" \approx 25', 8" \approx 1 mile

Invert Elevations: Entrance _____ Exit _____

Physical Condition (Describe): _____ Unobservable ✓

Material: _____

Joints: _____ Alignment _____

Structural Integrity: Appears to be intact

Hydraulic Capability: _____

Means of Control: Gate _____ Valve ✓ Uncontrolled _____

Operation: Operable ✓ Inoperable _____ Other _____

Present Condition (Describe): Good working order

9) Structural

- a. Concrete Surfaces generally good. Some Spalling
near line of ice contact.
- b. Structural Cracking None evident
- c. Movement - Horizontal & Vertical Alignment (Settlement) None
evident
- d. Junctions with Abutments or Embankments left Abutment
good - low saddle in Rt abutment near
contact.
- e. Drains - Foundation, Joint, Face None existent
- f. Water Passages, Conduits, Sluices appear to be good.
- g. Seepage or Leakage Small seepage from several
"cracks" in masonry on left non-overflow
section. Flow ranges from 1 to 3 gpm.
No fines in flow

- h. Joints - Construction, etc. Masonry joints are
generally in good condition. Some pointing has
been done in recent years
- i. Foundation Hardpan - generally sound
- j. Abutments lt abutment has low saddle
- k. Control Gates operable
- l. Approach & Outlet Channels Approach not visible, reported
to be good. Outlet - good condition
- m. Energy Dissipators (Plunge Pool, etc.) None
- n. Intake Structures Appears to be good - upstream
screen structure somewhat dilapidated
- o. Stability Appears stable
- p. Miscellaneous

HYDROLOGIC DATA AND COMPUTATION

APPENDIX D

TAMS

Job No. 1551-10
 Project GARNERVILLE DAM PHASE 1 INSPECTION
 Subject HYDROLOGIC/HYDRAULIC COMPUTATIONS
SUB AREA A

Sheet 1 of 6
 Date MAY 15 1980
 By D.L.C.
 Ch'k. by _____

$$\begin{aligned} T_p &= C_T (L L_a)^{0.3} \\ &= 2.525 [(7.1)(3.2)]^{0.3} \\ &= (2.525)(2.55) \\ &= 6.44 \end{aligned}$$

$$\begin{aligned} L &= 7.1 \text{ mi} \\ L &= 3.2 \text{ mi} \\ C_T &= 2.525 \\ C_p &= 0.625 \\ A &= 8.2 \text{ sq mi} \end{aligned}$$

use $t_n = 1 \text{ hour}$

$$\begin{aligned} q_p &= \frac{640 C_p}{T_p} \\ &= \frac{400}{6.44} \\ &= 62.1 \text{ cfs/sq mile} \end{aligned}$$

$$Q_p = 509.2 \text{ cfs.}$$

Initial loss 2"

Constant loss 0.1 inch/hour

TAMS

Job No. 1551-10

Project GARNEVILLE DAM PHASE 1 INSPECTION

Subject HYDROLOGIC / HYDRAULIC COMPUTATIONS

SUB BASIN B

Sheet 2 of 6

Date MAY 16 1960

By D. L. C

Ch'k. by _____

$$\begin{aligned}
 T_p &= C_T (L L_{CA})^{0.3} \\
 &= 2.67 [(5.7)(2.6)]^{0.3} \\
 &= 2.67 \times 2.245 \\
 &= 6.0 \text{ hours}
 \end{aligned}$$

$$\begin{aligned}
 L &= 5.7 \text{ mi} \\
 L_{CA} &= 2.6 \text{ mi} \\
 C_T &= 2.67 \\
 C_p &= 0.625 \\
 A &= 6.9 \text{ mi}^2
 \end{aligned}$$

Use $T_n = 1.0 \text{ hour}$

$$\begin{aligned}
 Q_{DP} &= \frac{640 C_p}{T_p} \cdot \frac{640 \times 0.625}{6.00} \\
 &= 66.7
 \end{aligned}$$

$$\begin{aligned}
 Q_p &= 66.7 \times 6.9 \\
 &= 460 \text{ cfs.}
 \end{aligned}$$

Initial loss 2.0"

Constant loss 0.1 in/hour.

TAMS

Job No. 1551-10

Project GARNERVILLE DAM

Subject HYDROLOGIC / HYDRAULIC COMPUTATIONS

SUB AREA C

Sheet 3 of 6

Date MAY 16 1960

By D.L.C.

Ch'k. by

$$T_p = C_T (L L_{CA})^{0.3}$$

$$= 2 [(2.4)(1.3)]^{0.3} = 2 \times 1.407$$

$$= 2.8 \text{ hrs}$$

$$L = 2.4 \text{ Mi.}$$

$$L_{CA} = 1.3 \text{ Mi.}$$

$$A = 2.4 \text{ SQ MI.}$$

$$T_h = 2.8 / T_p = 0.5 \text{ hours.}$$

$$\text{USE } t_R = 1.0$$

$$T_{PR} = t_p + 0.25(T_R - t_h)$$

$$= 2.8 + .25(.5)$$

$$= 2.925 \text{ hrs}$$

$$q_p = \frac{640 C_p}{T_p} = \frac{400}{2.8}$$

$$= 142.9 \text{ cfs/sq mile}$$

$$Q_p = 142.9 \times 2.4$$

$$= 342.8 \text{ cfs.}$$

$$q_{PR} = 136.7 \text{ cfs/sq m.}$$

$$C_{PR} = 328 \text{ cfs}$$

Cross-section for routing combined hydrographs from
Sub Areas A & B through Sub Area C

36+00		54+00		76+00		96+00		114+00	
STATION	ELEVATION	STATION	ELEVATION	STN	EL	STN	EL	STN	EL
7450	580			6800	320				
8150	560	6710	360	7460	350	5350	300	7290	250
8220	340	6750	300	7600	290	5520	270	7380	260
8250	325	6810	320	7710	270	5600	260	7460	260
8500	328	6820	315	8000	270	5800	240	7510	220
8540	340	7060	300	8020	280	6000	228	7540	210
8600	340	7000	310	8150	300	6100	210	7550	220
8600	340	7000	310	8200	320	6100	200	7550	230
8600	380	7000	300			6150	270	7550	220
		7410	300			6150	271	7550	220
						6200	220	7550	220
						6450	300	7550	220

TAMS

Job No. 1551-10

Project GARNERVILLE DAM PHASE 1 INSPECTION

Subject HYDROLOGIC / HYDRAULIC COMPUTATION

SPILLWAY RATING $C \approx 3.46$

Sheet 4 of 6

Date MAY 28 1990

By DLC

Ch'k. by _____

Assume Coef C reduced 10% due to poor condition of spillway surface

Use $C' = 3.114$

$Q = C' L H^{3/2}$

Flow over DAM

$L = 260$ $C' = 2.778$

$L = 690'$

E_L	H	$L \times C'$	Q	
210	0	214.87	0	
211	1		215	
212	2		608	
214	4		1720	
216	6		3160.	
216.9	6.9		3890.	TOP OF DAM
218	8		4860.	830.
220	10		6790.	3940 10730

P1 @ 24 HR 200 V.S. (15000)

24.5%

% Point 2M	CHIC	10.1	122.4	24 HR	45 HOUR	7.5
		100.1	122.4	134.7	151.0	157.1

TAMS

Job No. 1551-10

Project GARDINERVILLE DAM PHASE 1 INSPECTION


Subject EL/AREA/ SURCHARGE STORAGE.

Sheet 5 of 6

Date MAY 30 19

By DLC

Ch'k. by _____



EL	ZH	AREA	MEAN AREA	Σ VOL.	SURCHARGE STORAGE
(Ft)		(Ac)	(Ac)	(Acft)	(Acft)
210		10.2			0
	2		11.35	22.7	
212		12.5			22.7
	2		13.65	27.3	
214		14.8			50
	2		16.	33.0	
216		17.2			82
	2		18.35	36.7	
218		19.5			118.7
	2		20.65	41.3	
220		21.8			160.

Assume Vol of Dam at EL 210 (Normal Pond) = 100 Acft.

TAMS

Job No. 1551-10

Project GIARNEVILLE DAM PHASE I INSPECTION

Subject HYDROLOGIC/HYDRAULIC COMPUTATIONS

Sheet 6 of 6

Date JUNE 4 1990

By DLC

Ch'k. by _____

CROSS SECTIONS - from USGS QUADRANGLE MAP below DAM

STN 2+00

STATION	ELEV
1500	220
1590	200
1690	195
1730	194
1960	180
2000	175
2040	180
2140	200
2200	220

STN 22+00

STN	ELEVATION
6900	170
7300	160
7860	152
7900	151
7930	150
8000	140
8040	150
8180	160
8200	170

STN 24+00

6920	150
6940	140
6970	130
6980	120
7000	115
7030	120
7070	130
7100	140
7750	150

[illegible]

FW	C	QUEN	STR	JETW	ALCU	NS
				A		
				B		
				A P		
				1P+00		
				76+00		
				114+0		
				C		
				COMBINE 2 HYDROGRAPHS AT INFLOW		
				ROUTE HYDROGRAPH TO	100	
				ROUTE HYDROGRAPH TO	2+00	
				ROUTE HYDROGRAPH TO	39+00	
				END OF NETWORK		

 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1979
 LAST MODIFICATION 25 FEB 79

FILE DATE 07/ 7/23.
 TIME 10:22:07.

PHASE 1 INSPECTION GARNERVILLE DAM ROCKLAND COUNTY N.Y. 1551-10
 TAMS ENGINEERS AND ARCHITECTS
 MAY 1980

JOB SPECIFICATION									
NO	NHR	NMIN	IDAY	IHR	IMIN	METRC	IPLT	IPRT	NSTAN
100	1	0	0	0	0	0	0	0	0
	JOPEP	5		NWT	LROPT	TRACE			
				0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLAN= 1 NRTIO= 2 LRTIO= 1

RTIOS= 1.00 .50

 SUP-AREA RUNOFF COMPUTATION

SUP-AREA RUNOFF

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
A	0	0	0	1	0	1	0	0

HYDROGRAPH DATA

INVDG	IUNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	8.20	0.00	8.20	0.00	0.000	0	1	0

PRECIP DATA
 SPEP 6.00 PMS 21.00 R4 110.50 R12 122.00 R24 142.00
 TESTS CONVERTED BY THE PROGRAM IS 1.00

LEOPT	STKR	PLINE	RTIOL	ERAIN	STKRS	RTIOK	STRTL	CNSTL	ALSMX	RTIMP
0.00	0.00	1.00	0.00	0.00	1.00	2.00	0.00	.10	0.00	.05

UNIT HYDROGRAPH DATA
 TP= 6.44 CP= .63 NTA= 0

RECESSION DATA
 STKTR= -1.00 ORCSH= -1.50 RTIOR= 3.00
 APPROXIMATE CLAW COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC= 7.50 AND R= 5.92 INTERVALS

UNIT HYDROGRAPH OF END-OF-PERIOD COORDINATES- LAG= 6.50 HOURS, CP= .63 VOL= 1.00

20.	134.	27.	321.	423.	401.	516.	488.	422.	356.
21.	134.	27.	181.	153.	129.	100.	92.	78.	66.
22.	47.	27.	23.	23.	24.	20.	17.	14.	12.
23.	9.	7.	4.	5.	4.				

END-OF-PERIOD DATA

HYDROGRAPH AT STA A FOR PLAN 1, RTIO 1

TIME	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
7.	9221.	8322.	1729.	124809.
8.	261.	236.	49.	3537.
9.		9.44	23.54	23.62
10.		239.78	597.82	599.86
11.		4126.	10288.	10323.
12.		5090.	12690.	12733.

PEAK 9221. CFS
261. CFS
INCHES
AC-FT
THOUS CU M

HYDROGRAPH AT STA B FOR PLAN 1, RTIO 2

TIME	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
7.	4611.	4161.	864.	62454.
8.	131.	119.	24.	1765.
9.		4.72	11.77	11.81
10.		119.89	298.01	299.03
11.		2067.	5144.	5162.
12.		2545.	6345.	6367.

PEAK 4611. CFS
131. CFS
INCHES
AC-FT
THOUS CU M

SUP BASIN F RUNOFF

SUR-AREA RUNOFF COMPUTATION

ISTAQ	ICOMP	IFCON	ITAPE	JPLT	JPRF	INAME	ISTAGE	IAUTO
8	0	0	0	0	0	0	0	0

HYDROGRAPH DATA

INHC	INHC	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	1	6.00	0.50	6.00	0.00	0.000	0	1	0

PRECIP DATA

SNFF	PWS	PA	R12	R24	R48	R72	R96
0.00	21.90	110.50	172.00	132.00	142.00	0.00	0.00

LOSS DATA

LOSS	STAGE	TIME	RTIO	RTMP	ALSM	RTMP
0.00	21.90	110.50	172.00	132.00	142.00	0.00

LOSS COMPUTED BY THE PROGRAM IS .000

UNIT HYDROGRAPH DATA

TP= 6.00 CP= .63 NTA= 0

RECESSION DATA

STATUS= -1.00 GRCSN= -.50 RTIOR= 3.00
 UNIT HYDROGRAPH 33 END-OF-PERIOD COORDINATES, LAG= 5.98 HOURS, CP= .63 VOL= 1.00
 30. 109. 330. 422. 471. 466. 340. 282.
 234. 164. 111. 92. 63. 53. 44.
 36. 25. 17. 14. 12. 10. 7.
 4. 4.

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC= 6.26 AND R= 5.37 INTERVALS

W.D.P.	PERIOD	RAIN	EXCS	LOSS	COMP Q	END-OF-PERIOD FLOW	W.D.P.	PERIOD	RAIN	EXCS	LOSS	COMP Q
1.01	1.00	.01	.00	.01	6.	1.03	3.00	51	0.00	0.00	0.00	3970.
1.01	2.00	.01	.00	.01	6.	1.03	4.00	52	0.00	0.00	0.00	3557.
1.01	3.00	.01	.00	.01	5.	1.03	5.00	53	0.00	0.00	0.00	3187.
1.01	4.00	.01	.00	.01	5.	1.03	6.00	54	0.00	0.00	0.00	2855.
1.01	5.00	.01	.00	.01	4.	1.03	7.00	55	0.00	0.00	0.00	2558.
1.01	6.00	.01	.00	.01	4.	1.03	8.00	56	0.00	0.00	0.00	2292.
1.01	7.00	.03	.00	.02	4.	1.03	9.00	57	0.00	0.00	0.00	2053.
1.01	8.00	.03	.00	.02	4.	1.03	10.00	58	0.00	0.00	0.00	1840.
1.01	9.00	.03	.00	.02	3.	1.03	11.00	59	0.00	0.00	0.00	1648.
1.01	10.00	.02	.00	.02	3.	1.03	12.00	60	0.00	0.00	0.00	1477.
1.01	11.00	.02	.00	.02	3.	1.03	13.00	61	0.00	0.00	0.00	1323.
1.01	12.00	.02	.00	.02	4.	1.03	14.00	62	0.00	0.00	0.00	1186.
1.01	13.00	.15	.00	.14	4.	1.03	15.00	63	0.00	0.00	0.00	1062.
1.01	14.00	.18	.01	.17	4.	1.03	16.00	64	0.00	0.00	0.00	952.
1.01	15.00	.22	.01	.21	5.	1.03	17.00	65	0.00	0.00	0.00	853.
1.01	16.00	.56	.02	.54	7.	1.03	18.00	66	0.00	0.00	0.00	764.
1.01	17.00	.21	.01	.20	10.	1.03	19.00	67	0.00	0.00	0.00	684.
1.01	18.00	.16	.00	.16	13.	1.03	20.00	68	0.00	0.00	0.00	613.
1.01	19.00	.01	.00	.01	17.	1.03	21.00	69	0.00	0.00	0.00	549.
1.01	20.00	.01	.00	.01	19.	1.03	22.00	70	0.00	0.00	0.00	492.
1.01	21.00	.01	.00	.01	21.	1.03	23.00	71	0.00	0.00	0.00	441.
1.01	22.00	.01	.00	.01	20.	1.04	0.00	72	0.00	0.00	0.00	395.
1.01	23.00	.01	.00	.01	18.	1.04	1.00	73	0.00	0.00	0.00	354.
1.02	0.00	.01	.00	.01	16.	1.04	2.00	74	0.00	0.00	0.00	317.
1.02	1.00	.11	.00	.11	14.	1.04	3.00	75	0.00	0.00	0.00	284.
1.02	2.00	.12	.00	.11	12.	1.04	4.00	76	0.00	0.00	0.00	255.
1.02	3.00	.12	.02	.10	12.	1.04	5.00	77	0.00	0.00	0.00	228.
1.02	4.00	.12	.02	.10	13.	1.04	6.00	78	0.00	0.00	0.00	204.
1.02	5.00	.12	.02	.10	16.	1.04	7.00	79	0.00	0.00	0.00	183.
1.02	6.00	.12	.02	.10	22.	1.04	8.00	80	0.00	0.00	0.00	164.
1.02	7.00	.34	.24	.10	36.	1.04	9.00	81	0.00	0.00	0.00	147.
1.02	8.00	.34	.24	.10	68.	1.04	10.00	82	0.00	0.00	0.00	132.
1.02	9.00	.34	.24	.10	123.	1.04	11.00	83	0.00	0.00	0.00	118.
1.02	10.00	.74	.24	.10	203.	1.04	12.00	84	0.00	0.00	0.00	106.
1.02	11.00	.74	.24	.10	301.	1.04	13.00	85	0.00	0.00	0.00	95.
1.02	12.00	.34	.24	.10	409.	1.04	14.00	86	0.00	0.00	0.00	85.
1.02	13.00	1.94	1.84	.10	567.	1.04	15.00	87	0.00	0.00	0.00	76.
1.02	14.00	2.32	2.23	.10	843.	1.04	16.00	88	0.00	0.00	0.00	68.
1.02	15.00	2.40	2.21	.10	1325.	1.04	17.00	89	0.00	0.00	0.00	61.
1.02	16.00	7.16	7.26	.10	2197.	1.04	18.00	90	0.00	0.00	0.00	55.
1.02	17.00	4.8	2.71	.10	3526.	1.04	19.00	91	0.00	0.00	0.00	49.
1.02	18.00	4.2	2.13	.10	5114.	1.04	20.00	92	0.00	0.00	0.00	44.
1.02	19.00	.18	.02	.10	6666.	1.04	21.00	93	0.00	0.00	0.00	39.
1.02	20.00	.18	.02	.10	7815.	1.04	22.00	94	0.00	0.00	0.00	35.
1.02	21.00	.18	.08	.10	8336.	1.04	23.00	95	0.00	0.00	0.00	32.
1.02	22.00	.18	.08	.10	8178.	1.05	0.00	96	0.00	0.00	0.00	28.
1.02	23.00	.18	.08	.10	7442.	1.05	1.00	97	0.00	0.00	0.00	25.
1.02	24.00	.18	.08	.10	6441.	1.05	2.00	98	0.00	0.00	0.00	23.

COMP UNCL IM S. INS
 ISTAG ICOMP IECON ITAPE JFLT JPRT INAME ISTAGE IAUTO
 A R 2 0 0 1 0 0

SUM OF 2 HYDROGRAPHS AT A B PLAN 1 RTIO 1
 12. 11. 10. 9. 9. 8.
 5. 9. 11. 14. 26. 36.
 57. 54. 48. 42. 37. 43.
 52. 54. 48. 42. 37. 43.
 146. 254. 414. 613. 835. 1152. 1721. 2888. 4421.
 10276. 13489. 16016. 17365. 17400. 16214. 14316. 12286. 10420.
 7637. 1107. 6367. 5705. 5111. 4579. 4103. 3676. 3294.
 2651. 2444. 2122. 1902. 1704. 1526. 1368. 1225. 1088.
 944. 790. 707. 634. 568. 509. 456. 408. 366.
 322. 294. 263. 211. 189. 170. 152. 136. 122.
 106. 88. 79. 67. 57. 51. 45. 41. 36.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME
 CFS 17400. 8509. 3224. 232792.
 CMS 493. 241. 91. 6592.
 INCHES 9.67 20.97 23.83 27.90
 WM 245.46 522.61 605.35 607.11
 AC-FT 7785. 16878. 19187. 19239.
 THOUS CU M 9603. 20619. 23662. 23731.

SUM OF 2 HYDROGRAPHS AT A P PLAN 1 RTIO 2
 7. 6. 5. 5. 4. 4.
 4. 5. 5. 7. 9. 18.
 25. 27. 24. 21. 19. 18.
 41. 126. 207. 306. 417. 576. 861. 1344. 2211.
 3536. 6745. 8008. 8482. 8700. 8107. 7158. 6143. 5210.
 3968. 3553. 3184. 2852. 2536. 2290. 2051. 1838. 1647.
 1475. 1184. 1161. 851. 857. 763. 684. 540. 483.
 441. 395. 354. 317. 284. 254. 228. 204. 183.
 164. 132. 118. 106. 95. 85. 76. 68. 61.
 49. 44. 39. 35. 32. 28. 25. 23. 20.

PEAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME
 CFS 8700. 7850. 4255. 1612. 116396.
 CMS 246. 222. 120. 46. 3296.
 INCHES 4.84 10.48 11.92 11.05
 WM 122.87 266.31 302.68 303.55
 AC-FT 3692. 8439. 9592. 9620.
 THOUS CU M 4601. 10410. 11831. 11865.

HYDROGRAPH ROUTING

WINICEONGO CREEK CHANNEL ROUTING

ISTAG ICOMP IECON ITAPE JFLT JPRT INAME ISTAGE IAUTO
 1E+00 1 0 0 0 0 0 0
 GLOSS CROSS AVG IRFS ISAME IOPT IPMP LSTR
 0.0 0.00 0.00 1 1 0 0
 ASTPS NSTDL LAG AMSKK X TSK STORA ISPRAT
 1 0 0 0.000 0.000 0.000 0.000 0.000 0.000

FLVLT	FLMAX	RLNTH	SFL
44(2)	389.0	3600.	.00500
51(2)	372.0		

CRACKS SECTION COORDINATES--STA,ELEV,STA,FLEV--ETC
750.0 320.00 423.00 320.00 4220.00 340.00
1320.0 320.70 445.00 370.00 4630.00 380.00

[illegible]

STATION 10+00, PLAN 1, RTIO 1

OUTFLOW		STOR	
17.	12.	12.	0.
18.	9.	9.	0.
19.	5.	5.	0.
20.	4.	4.	0.
21.	3.	3.	0.
22.	2.	2.	0.
23.	1.	1.	0.
24.	0.	0.	0.
25.	0.	0.	0.
26.	0.	0.	0.
27.	0.	0.	0.
28.	0.	0.	0.
29.	0.	0.	0.
30.	0.	0.	0.
31.	0.	0.	0.
32.	0.	0.	0.
33.	0.	0.	0.
34.	0.	0.	0.
35.	0.	0.	0.
36.	0.	0.	0.
37.	0.	0.	0.
38.	0.	0.	0.
39.	0.	0.	0.
40.	0.	0.	0.
41.	0.	0.	0.
42.	0.	0.	0.
43.	0.	0.	0.
44.	0.	0.	0.
45.	0.	0.	0.
46.	0.	0.	0.
47.	0.	0.	0.
48.	0.	0.	0.
49.	0.	0.	0.
50.	0.	0.	0.
51.	0.	0.	0.
52.	0.	0.	0.
53.	0.	0.	0.
54.	0.	0.	0.
55.	0.	0.	0.
56.	0.	0.	0.
57.	0.	0.	0.
58.	0.	0.	0.
59.	0.	0.	0.
60.	0.	0.	0.
61.	0.	0.	0.
62.	0.	0.	0.
63.	0.	0.	0.
64.	0.	0.	0.
65.	0.	0.	0.
66.	0.	0.	0.
67.	0.	0.	0.
68.	0.	0.	0.
69.	0.	0.	0.
70.	0.	0.	0.
71.	0.	0.	0.
72.	0.	0.	0.
73.	0.	0.	0.
74.	0.	0.	0.
75.	0.	0.	0.
76.	0.	0.	0.
77.	0.	0.	0.
78.	0.	0.	0.
79.	0.	0.	0.
80.	0.	0.	0.
81.	0.	0.	0.
82.	0.	0.	0.
83.	0.	0.	0.
84.	0.	0.	0.
85.	0.	0.	0.
86.	0.	0.	0.
87.	0.	0.	0.
88.	0.	0.	0.
89.	0.	0.	0.
90.	0.	0.	0.
91.	0.	0.	0.
92.	0.	0.	0.
93.	0.	0.	0.
94.	0.	0.	0.
95.	0.	0.	0.
96.	0.	0.	0.
97.	0.	0.	0.
98.	0.	0.	0.
99.	0.	0.	0.
100.	0.	0.	0.

STAGE

STRAPE	
328.1	328.1
328.1	328.1
328.3	328.3
328.3	328.3
328.4	328.4
328.4	328.4
328.5	328.5
328.5	328.5
328.6	328.6
328.6	328.6
328.7	328.7
328.7	328.7
328.8	328.8
328.8	328.8
328.9	328.9
328.9	328.9
329.0	329.0
329.0	329.0
329.1	329.1
329.1	329.1
329.2	329.2
329.2	329.2
329.3	329.3
329.3	329.3
329.4	329.4
329.4	329.4
329.5	329.5
329.5	329.5
329.6	329.6
329.6	329.6
329.7	329.7
329.7	329.7
329.8	329.8
329.8	329.8
329.9	329.9
329.9	329.9
330.0	330.0
330.0	330.0
330.1	330.1
330.1	330.1
330.2	330.2
330.2	330.2
330.3	330.3
330.3	330.3
330.4	330.4
330.4	330.4
330.5	330.5
330.5	330.5
330.6	330.6
330.6	330.6
330.7	330.7
330.7	330.7
330.8	330.8
330.8	330.8
330.9	330.9
330.9	330.9
331.0	331.0
331.0	331.0
331.1	331.1
331.1	331.1
331.2	331.2
331.2	331.2
331.3	331.3
331.3	331.3
331.4	331.4
331.4	331.4
331.5	331.5
331.5	331.5
331.6	331.6
331.6	331.6
331.7	331.7
331.7	331.7
331.8	331.8
331.8	331.8
331.9	331.9
331.9	331.9
332.0	332.0
332.0	332.0
332.1	332.1
332.1	332.1
332.2	332.2
332.2	332.2
332.3	332.3
332.3	332.3
332.4	332.4
332.4	332.4
332.5	332.5
332.5	332.5
332.6	332.6
332.6	332.6
332.7	332.7
332.7	332.7
332.8	332.8
332.8	332.8
332.9	332.9
332.9	332.9
333.0	333.0
333.0	333.0
333.1	333.1
333.1	333.1
333.2	333.2
333.2	333.2
333.3	333.3
333.3	333.3
333.4	333.4
333.4	333.4
333.5	333.5
333.5	333.5
333.6	333.6
333.6	333.6
333.7	333.7
333.7	333.7
333.8	333.8
333.8	333.8
333.9	333.9
333.9	333.9
334.0	334.0
334.0	334.0
334.1	334.1
334.1	334.1
334.2	334.2
334.2	334.2
334.3	334.3
334.3	334.3
334.4	334.4
334.4	334.4
334.5	334.5
334.5	334.5
334.6	334.6
334.6	334.6
334.7	334.7
334.7	334.7
334.8	334.8
334.8	334.8
334.9	334.9
334.9	334.9
335.0	335.0
335.0	335.0
335.1	335.1
335.1	335.1
335.2	335.2
335.2	335.2
335.3	335.3
335.3	335.3
335.4	335.4
335.4	335.4
335.5	335.5
335.5	335.5
335.6	335.6
335.6	335.6
335.7	335.7
335.7	335.7
335.8	335.8
335.8	335.8
335.9	335.9
335.9	335.9
336.0	336.0
336.0	336.0
336.1	336.1
336.1	336.1
336.2	336.2
336.2	336.2
336.3	336.3

THE UNIVERSITY OF CHICAGO

ST 73415 4101A4a

[illegible]

HYDROGRAPH ROUTING

CHANNEL FULTON MINISCENO CREEK

INSTAQ	ICOMP	IFCON	ITAPE	JPLT	JPRP	INAME	ISTAGE	TAUTO
06+10	1	0	0	0	0	0	0	0
			ROUTING DATA					
CLOSS	AVG	IRCS	ISAME	IOPT	IPMP		LSTR	
0.000	0.00	1	1	0	0		0	
NSTPS	NSTDL	LAG	AMSKY	X	TSK	STORA	ISPRAT	
1	0	0	0.000	0.000	0.000	0.	0	

SECRET 730447-47 730447-47

COG(1)	COG(2)	COG(3)	FLNVT	FLMAX	RLNTH	SEL
0.0000	0.0000	0.0000	270.0	320.0	4000.	.01400

COORS	SECTION	COORDINATES	STA	ELEV	STA	ELEV	ETC
441.0		520.00	7640.00	350.00	7640.00	290.00	7
442.0		250.00	4150.00	375.00	8300.00	320.00	

	ST-132	ST-133	ST-134	ST-135	ST-136	ST-137	ST-138	ST-139	ST-140	ST-141	ST-142	ST-143	ST-144	ST-145	ST-146	ST-147	ST-148	ST-149	ST-150	ST-151	ST-152	ST-153	ST-154	ST-155	ST-156	ST-157	ST-158	ST-159	ST-160	ST-161	ST-162	ST-163	ST-164	ST-165	ST-166	ST-167	ST-168	ST-169	ST-170	ST-171	ST-172	ST-173	ST-174	ST-175	ST-176	ST-177	ST-178	ST-179	ST-180	ST-181	ST-182	ST-183	ST-184	ST-185	ST-186	ST-187	ST-188	ST-189	ST-190	ST-191	ST-192	ST-193	ST-194	ST-195	ST-196	ST-197	ST-198	ST-199	ST-200	ST-201	ST-202	ST-203	ST-204	ST-205	ST-206	ST-207	ST-208	ST-209	ST-210	ST-211	ST-212	ST-213	ST-214	ST-215	ST-216	ST-217	ST-218	ST-219	ST-220	ST-221	ST-222	ST-223	ST-224	ST-225	ST-226	ST-227	ST-228	ST-229	ST-230	ST-231	ST-232	ST-233	ST-234	ST-235	ST-236	ST-237	ST-238	ST-239	ST-240	ST-241	ST-242	ST-243	ST-244	ST-245	ST-246	ST-247	ST-248	ST-249	ST-250	ST-251	ST-252	ST-253	ST-254	ST-255	ST-256	ST-257	ST-258	ST-259	ST-260	ST-261	ST-262	ST-263	ST-264	ST-265	ST-266	ST-267	ST-268	ST-269	ST-270	ST-271	ST-272	ST-273	ST-274	ST-275	ST-276	ST-277	ST-278	ST-279	ST-280	ST-281	ST-282	ST-283	ST-284	ST-285	ST-286	ST-287	ST-288	ST-289	ST-290	ST-291	ST-292	ST-293	ST-294	ST-295	ST-296	ST-297	ST-298	ST-299	ST-300	ST-301	ST-302	ST-303	ST-304	ST-305	ST-306	ST-307	ST-308	ST-309	ST-310	ST-311	ST-312	ST-313	ST-314	ST-315	ST-316	ST-317	ST-318	ST-319	ST-320	ST-321	ST-322	ST-323	ST-324	ST-325	ST-326	ST-327	ST-328	ST-329	ST-330	ST-331	ST-332	ST-333	ST-334	ST-335	ST-336	ST-337	ST-338	ST-339	ST-340	ST-341	ST-342	ST-343	ST-344	ST-345	ST-346	ST-347	ST-348	ST-349	ST-350	ST-351	ST-352	ST-353	ST-354	ST-355	ST-356	ST-357	ST-358	ST-359	ST-360	ST-361	ST-362	ST-363	ST-364	ST-365	ST-366	ST-367	ST-368	ST-369	ST-370	ST-371	ST-372	ST-373	ST-374	ST-375	ST-376	ST-377	ST-378	ST-379	ST-380	ST-381	ST-382	ST-383	ST-384	ST-385	ST-386	ST-387	ST-388	ST-389	ST-390	ST-391	ST-392	ST-393	ST-394	ST-395	ST-396	ST-397	ST-398	ST-399	ST-400	ST-401	ST-402	ST-403	ST-404	ST-405	ST-406	ST-407	ST-408	ST-409	ST-410	ST-411	ST-412	ST-413	ST-414	ST-415	ST-416	ST-417	ST-418	ST-419	ST-420	ST-421	ST-422	ST-423	ST-424	ST-425	ST-426	ST-427	ST-428	ST-429	ST-430	ST-431	ST-432	ST-433	ST-434	ST-435	ST-436	ST-437	ST-438	ST-439	ST-440	ST-441	ST-442	ST-443	ST-444	ST-445	ST-446	ST-447	ST-448	ST-449	ST-450	ST-451	ST-452	ST-453	ST-454	ST-455	ST-456	ST-457	ST-458	ST-459	ST-460	ST-461	ST-462	ST-463	ST-464	ST-465	ST-466	ST-467	ST-468	ST-469	ST-470	ST-471	ST-472	ST-473	ST-474	ST-475	ST-476	ST-477	ST-478	ST-479	ST-480	ST-481	ST-482	ST-483	ST-484	ST-485	ST-486	ST-487	ST-488	ST-489	ST-490	ST-491	ST-492	ST-493	ST-494	ST-495	ST-496	ST-497	ST-498	ST-499	ST-500	ST-501	ST-502	ST-503	ST-504	ST-505	ST-506	ST-507	ST-508	ST-509	ST-510	ST-511	ST-512	ST-513	ST-514	ST-515	ST-516	ST-517	ST-518	ST-519	ST-520	ST-521	ST-522	ST-523	ST-524	ST-525	ST-526	ST-527	ST-528	ST-529	ST-530	ST-531	ST-532	ST-533	ST-534	ST-535	ST-536	ST-537	ST-538	ST-539
--	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------

STATION 76+00, PLAN 1, RYIO 1

	OUTFLOW				STOR			
	11.	12.	11.	9.	0.	8.	8.	
24.	9.	9.	17.	16.	22.	31.	49.	
5.	56.	56.	51.	40.	36.	40.	48.	
55.	111.	105.	320.	777.	1047.	2371.	3949.	
67.	5619.	13136.	15661.	17455.	16452.	13569.	10678.	
72.	9619.	22725.	6503.	5219.	4685.	4190.	3576.	
74.	111.	7245.	6503.	5219.	4685.	4190.	3576.	
75.	274.	2445.	2180.	1757.	1578.	1411.	1133.	
76.	11.	116.	11.	87.	571.	477.	389.	
77.	312.	279.	250.	201.	180.	161.	129.	
78.	704.	93.	83.	67.	60.	56.	43.	
	0.	0.	0.	0.	0.	0.	0.	
	0.	0.	0.	0.	0.	1.	1.	

MAXIMUM STORAGE = 55.

★ ★ ★ ★ ★

金
大
正
十
五
年
十
月
十
日

7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
841
842
843
844

SUB-AREA RUNOFF COMPUTATION

SUB-FAS IN C RUNOFF

```

IYDG      1
IUNG      1
TAREA     2.40
SNAP      0.00
TRSDA     2.40
TRSPC     0.00
RATIO     0.000
HYDROGRAPH DATA
ISNOW     0
ISAME     1
LOCAL     0
JPR1      0
ISTAGE     0
JPLT      1
ITAPE     0
IECON     0
ICOMP     0
ISTAQ     0
PRECIP DATA
R6        110.50
R12       122.00
R24       132.00
R48       142.00
R72       0.00
R96       0.00
SPE       21.90
PMS       0.00
TIME     15.800
TIMESE COMPUTED BY THE PROGRAM IS 15.800

```

SLIP	STKRS	OLTR	RTOL	ERAIN	STKRS	RTIOK	STRTL	CNSTL	ALSMX	RTIMP
0	0.00	1.00	0.00	0.00	1.00	1.00	0.00	0.00	0.00	0.01

APPROXIMATE CREEK COEFFICIENTS FROM GIVEN SNYDER CP AND IP ARE IC = 3.61 AND R = 2.35 INTERVALS

UNIT HYDROGRAPH IF END-OF-PERIOD ORIGINATES, LAG = 2.91 HOURS, CP = .62 VOL = 1.00
 56. 193. 314. 7. 5. 27.
 12. 11. 3. 42. 64. 98.

MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q	MO.DA	HR.MN	PERIOD	RAIN	EXCS	LOSS	COMP Q
1-01	1-00	1	.01	.00	.01	2.	1-03	3-00	51	0.00	0.00	0.00	1309.
1-01	2-00	2	.01	.00	.01	2.	1-03	4-00	52	0.00	0.00	0.00	1173.
1-01	3-00	3	.01	.00	.01	2.	1-03	5-00	53	0.00	0.00	0.00	1051.
1-01	4-00	4	.01	.00	.01	2.	1-03	6-00	54	0.00	0.00	0.00	941.
1-01	5-00	5	.01	.00	.01	1.	1-03	7-00	55	0.00	0.00	0.00	844.
1-01	6-00	6	.01	.00	.01	1.	1-03	8-00	56	0.00	0.00	0.00	756.
1-01	7-00	7	.01	.00	.01	1.	1-03	9-00	57	0.00	0.00	0.00	677.
1-01	8-00	8	.01	.00	.01	1.	1-03	10-00	58	0.00	0.00	0.00	607.
1-01	9-00	9	.01	.00	.01	1.	1-03	11-00	59	0.00	0.00	0.00	544.
1-01	10-00	10	.03	.00	.03	1.	1-03	12-00	60	0.00	0.00	0.00	487.
1-01	11-00	11	.03	.00	.03	1.	1-03	13-00	61	0.00	0.00	0.00	436.
1-01	12-00	12	.03	.00	.03	1.	1-03	14-00	62	0.00	0.00	0.00	391.
1-01	13-00	13	.15	.00	.15	1.	1-03	15-00	63	0.00	0.00	0.00	350.
1-01	14-00	14	.18	.00	.18	1.	1-03	16-00	64	0.00	0.00	0.00	314.
1-01	15-00	15	.22	.00	.22	2.	1-03	17-00	65	0.00	0.00	0.00	281.
1-01	16-00	16	.56	.25	.30	16.	1-03	18-00	66	0.00	0.00	0.00	252.
1-01	17-00	17	.21	.11	.10	57.	1-03	19-00	67	0.00	0.00	0.00	226.
1-01	18-00	18	.16	.06	.10	106.	1-03	20-00	68	0.00	0.00	0.00	202.
1-01	19-00	19	.01	.00	.01	128.	1-03	21-00	69	0.00	0.00	0.00	181.
1-01	20-00	20	.01	.00	.01	114.	1-03	22-00	70	0.00	0.00	0.00	162.
1-01	21-00	21	.01	.00	.01	84.	1-03	23-00	71	0.00	0.00	0.00	145.
1-01	22-00	22	.01	.00	.01	62.	1-04	0-00	72	0.00	0.00	0.00	130.
1-01	23-00	23	.01	.00	.01	56.	1-04	1-00	73	0.00	0.00	0.00	117.
1-02	0-00	24	.01	.00	.01	50.	1-04	2-00	74	0.00	0.00	0.00	105.
1-02	1-00	25	.12	.02	.10	45.	1-04	3-00	75	0.00	0.00	0.00	94.
1-02	2-00	26	.12	.02	.10	40.	1-04	4-00	76	0.00	0.00	0.00	84.
1-02	3-00	27	.12	.02	.10	36.	1-04	5-00	77	0.00	0.00	0.00	75.
1-02	4-00	28	.12	.02	.10	32.	1-04	6-00	78	0.00	0.00	0.00	67.
1-02	5-00	29	.12	.02	.10	29.	1-04	7-00	79	0.00	0.00	0.00	60.
1-02	6-00	30	.12	.02	.10	26.	1-04	8-00	80	0.00	0.00	0.00	54.
1-02	7-00	31	.14	.04	.10	37.	1-04	9-00	81	0.00	0.00	0.00	48.
1-02	8-00	32	.14	.04	.10	80.	1-04	10-00	82	0.00	0.00	0.00	43.
1-02	9-00	33	.14	.04	.10	150.	1-04	11-00	83	0.00	0.00	0.00	39.
1-02	10-00	34	.14	.04	.10	220.	1-04	12-00	84	0.00	0.00	0.00	35.
1-02	11-00	35	.14	.04	.10	271.	1-04	13-00	85	0.00	0.00	0.00	31.
1-02	12-00	36	.14	.04	.10	305.	1-04	14-00	86	0.00	0.00	0.00	28.
1-02	13-00	37	1.94	1.24	.70	416.	1-04	15-00	87	0.00	0.00	0.00	25.
1-02	14-00	38	2.32	2.22	.10	761.	1-04	16-00	88	0.00	0.00	0.00	22.
1-02	15-00	39	2.32	2.22	.10	1381.	1-04	17-00	89	0.00	0.00	0.00	20.
1-02	16-00	40	7.36	7.26	.10	2380.	1-04	18-00	90	0.00	0.00	0.00	18.
1-02	17-00	41	2.71	2.41	.30	3664.	1-04	19-00	91	0.00	0.00	0.00	16.
1-02	18-00	42	2.13	2.13	.00	4653.	1-04	20-00	92	0.00	0.00	0.00	14.
1-02	19-00	43	.16	.06	.10	4741.	1-04	21-00	93	0.00	0.00	0.00	13.
1-02	20-00	44	.18	.08	.10	3969.	1-04	22-00	94	0.00	0.00	0.00	12.
1-02	21-00	45	.18	.08	.10	2910.	1-04	23-00	95	0.00	0.00	0.00	10.
1-02	22-00	46	.18	.08	.10	2267.	1-05	0-00	96	0.00	0.00	0.00	9.
1-02	23-00	47	.18	.08	.10	2031.	1-05	1-00	97	0.00	0.00	0.00	8.
1-02	0-00	48	.18	.08	.10	1820.	1-05	2-00	98	0.00	0.00	0.00	7.
1-02	1-00	49	.18	.08	.10	1631.	1-05	3-00	99	0.00	0.00	0.00	7.
1-02	2-00	50	0.00	0.00	0.00	1461.	1-05	4-00	100	0.00	0.00	0.00	6.

SUM 24.88 21.18 3.70 48575.
 (632.) (538.) (94.) (1375.49)

FFAK 6-HOUR 24-HOUR 72-HOUR TOTAL VOLUME

[illegible]

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL
CFS	270.	1855.	885.	336.	24886.
CFS	67.	53.	25.	10.	688.
INCHES		17.72	15.63		15.60
INCHES		182.42	348.52	397.03	398.49
AC-FT		920.	1755.	2000.	2007.
AC-FT		1135.	2165.	2467.	2476.


COMBINE HYDROGRAPHS


CARBETANE CHANNEL FLOW 2 SIERRASIN RUNOFF AT STN 114+00.

ISTAG	ICOMP	IECON	ITAPE	JPLT	JPRY	INAME	ISTAGE	IAUTO
INFLW	2	0	0	2	1	1	0	0

SUM OF 2 HYDROGRAPHS AT INFLOW PLAN 1 RTIO 1

INFLW(I), OUTFLOW(O) AND OBSERVED FLOW(*)






• CUF •

STATION IN FLOW

INFLW (1), OUTFLOW (2) AND OBSERVED FLOW (3)



HYDROGRAPH ROUTING

RESERVOIR ROUTING GARNESVILLE DAM

ISTAG ICOMP IECON ITAPE JPLI JPRT INAME ISTAGE IAUTO
100 1 0 0 1 0 1 0 0

ROUTING DATA

QLOSS CLOSS AVG IRES ISAME ICPT IPMP LSTR
0.0 0.000 0.00 1 1 0 0 0

RSPTS NSTBL LAG AMSKK X ISK STORA ISPRAY
1 0 0 0.000 0.000 0.000 100. -1

STAGE 185.00 210.00 212.00 214.00 216.00 218.00 220.00

FLOW 0.00 0.00 602.00 1720.00 3160.00 4860.00 6790.00

CAPACITY= 0. 100. 123. 150. 182. 219. 260.

ELEVATION= 185. 210. 212. 214. 216. 218. 220.

CRFL SPWTD CROW EYPM FLEVEL COQL CAREA EXPL
210.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA

TOPEL COQD EXPD DAMWID
216.9 2.8 1.5 260.

STATION 100, PLAN 1, PATIO 1

END-OF-PERIOD HYDROGRAPH ORDINATES

OUTFLOW		STORAGE	
72.	27.	121.	101.
9.	9.	100.	100.
140.	123.	100.	100.
147.	115.	104.	104.
17731.	200.	110.	110.
17467.	436.	116.	116.
19481.	669.	124.	124.
19481.	19481.	130.	130.
20080.	20080.	136.	136.
20080.	20080.	142.	142.
20080.	20080.	148.	148.
20080.	20080.	154.	154.
20080.	20080.	160.	160.
20080.	20080.	166.	166.
20080.	20080.	172.	172.
20080.	20080.	178.	178.
20080.	20080.	184.	184.
20080.	20080.	190.	190.
20080.	20080.	196.	196.
20080.	20080.	202.	202.
20080.	20080.	208.	208.
20080.	20080.	214.	214.
20080.	20080.	220.	220.
20080.	20080.	226.	226.
20080.	20080.	232.	232.
20080.	20080.	238.	238.
20080.	20080.	244.	244.
20080.	20080.	250.	250.
20080.	20080.	256.	256.
20080.	20080.	262.	262.
20080.	20080.	268.	268.
20080.	20080.	274.	274.
20080.	20080.	280.	280.
20080.	20080.	286.	286.
20080.	20080.	292.	292.
20080.	20080.	298.	298.
20080.	20080.	304.	304.
20080.	20080.	310.	310.
20080.	20080.	316.	316.
20080.	20080.	322.	322.
20080.	20080.	328.	328.
20080.	20080.	334.	334.
20080.	20080.	340.	340.
20080.	20080.	346.	346.
20080.	20080.	352.	352.
20080.	20080.	358.	358.
20080.	20080.	364.	364.
20080.	20080.	370.	370.
20080.	20080.	376.	376.
20080.	20080.	382.	382.
20080.	20080.	388.	388.
20080.	20080.	394.	394.
20080.	20080.	400.	400.
20080.	20080.	406.	406.
20080.	20080.	412.	412.
20080.	20080.	418.	418.
20080.	20080.	424.	424.
20080.	20080.	430.	430.
20080.	20080.	436.	436.
20080.	20080.	442.	442.
20080.	20080.	448.	448.
20080.	20080.	454.	454.
20080.	20080.	460.	460.
20080.	20080.	466.	466.
20080.	20080.	472.	472.
20080.	20080.	478.	478.
20080.	20080.	484.	484.
20080.	20080.	490.	490.
20080.	20080.	496.	496.
20080.	20080.	502.	502.
20080.	20080.	508.	508.
20080.	20080.	514.	514.
20080.	20080.	520.	520.
20080.	20080.	526.	526.
20080.	20080.	532.	532.
20080.	20080.	538.	538.
20080.	20080.	544.	544.
20080.	20080.	550.	550.
20080.	20080.	556.	556.
20080.	20080.	562.	562.
20080.	20080.	568.	568.
20080.	20080.	574.	574.
20080.	20080.	580.	580.
20080.	20080.	586.	586.
20080.	20080.	592.	592.
20080.	20080.	598.	598.
20080.	20080.	604.	604.
20080.	20080.	610.	610.
20080.	20080.	616.	616.
20080.	20080.	622.	622.
20080.	20080.	628.	628.
20080.	20080.	634.	634.
20080.	20080.	640.	640.
20080.	20080.	646.	646.
20080.	20080.	652.	652.
20080.	20080.	658.	658.
20080.	20080.	664.	664.
20080.	20080.	670.	670.
20080.	20080.	676.	676.
20080.	20080.	682.	682.
20080.	20080.	688.	688.
20080.	20080.	694.	694.
20080.	20080.	700.	700.
20080.	20080.	706.	706.
20080.	20080.	712.	712.
20080.	20080.	718.	718.
20080.	20080.	724.	724.
20080.	20080.	730.	730.
20080.	20080.	736.	736.
20080.	20080.	742.	742.
20080.	20080.	748.	748.
20080.	20080.	754.	754.
20080.	20080.	760.	760.
20080.	20080.	766.	766.
20080.	20080.	772.	772.
20080.	20080.	778.	778.
20080.	20080.	784.	784.
20080.	20080.	790.	790.
20080.	20080.	796.	796.
20080.	20080.	802.	802.
20080.	20080.	808.	808.
20080.	20080.	814.	814.
20080.	20080.	820.	820.
20080.	20080.	826.	826.
20080.	20080.	832.	832.
20080.	20080.	838.	838.
20080.	20080.	844.	844.
20080.	20080.	850.	850.
20080.	20080.	856.	856.
20080.	20080.	862.	862.
20080.	20080.	868.	868.
20080.	20080.	874.	874.
20080.	20080.	880.	880.
20080.	20080.	886.	886.
20080.	20080.	892.	892.
20080.	20080.	898.	898.
20080.	20080.	904.	904.
20080.	20080.	910.	910.
20080.	20080.	916.	916.
20080.	20080.	922.	922.
20080.	20080.	928.	928.
20080.	20080.	934.	934.
20080.	20080.	940.	940.
20080.	20080.	946.	946.
20080.	20080.	952.	952.
20080.	20080.	958.	958.
20080.	20080.	964.	964.
20080.	20080.	970.	970.
20080.	20080.	976.	976.
20080.	20080.	982.	982.
20080.	20080.	988.	988.
20080.	20080.	994.	994.
20080.	20080.	1000.	1000.

PLAN
 500.
 257.
 FS
 512.
 241.
 CVC
 145.
 INCHES
 4.90
 10.89
 12.41
 315.14
 315.55
 124.54
 276.67
 11674.
 11626.
 4574.
 10161.
 12533.
 14276.
 THOUS CU M
 5642.
 14340.

VOLUME
 140672.
 7993.
 12.46
 315.55
 11626.
 14340.

HYDROGRAPH ROUTING

WINISGEORG CREEK D/S OF DAY

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRI	INAME	ISTAGE	IAUTO
2+00	1	0	0	0	0	0	0	0
ROUTING DATA								
GROSS	AVG	IRIS	ISAME	IOPT	IPMP		LSTR	
0.0	0.00	1	1	0	0		0	
NSTPS NSTDL LAG ANSKK X TSK STORA ISPRAT								
1	0	0	0.000	0.000	0.000	0.	0.	0

NORMAL DEPTH CHANNEL ROUTING

STATION	GN(1)	GN(2)	GN(3)	FLRVT	ELMAX	RLNTH	SFL
0+00	0.00	0.00	0.00	175.0	220.0	200.	.02100

CROSS SECTION COORDINATES--STA+FLRVT,STA+ELEV--ETC
 250.00 220.00 190.00 200.00 150.00 195.00 1730.00 194.00 1960.00 180.00
 250.00 175.00 2040.00 180.00 2140.00 206.00

STORAGE	OUTFLOW	STAGE	FLOW	STATION	2+00	PLAN 1	PTIO 1
0.00	25.52	269.74	177.37	0.	25.	0.	0.
25.52	31.41	269.74	177.37	25.	18.	25.	19.
50.00	37.50	269.74	177.37	50.	3.	50.	159.
75.00	43.71	269.74	177.37	75.	102.	75.	3252.
100.00	49.92	269.74	177.37	100.	81.	100.	14460.
125.00	56.13	269.74	177.37	125.	432.	125.	4410.
150.00	62.34	269.74	177.37	150.	20082.	150.	3966.
175.00	68.55	269.74	177.37	175.	6799.	175.	1514.
200.00	74.76	269.74	177.37	200.	7575.	200.	1352.
225.00	80.97	269.74	177.37	225.	2598.	225.	468.
250.00	87.18	269.74	177.37	250.	870.	250.	178.
275.00	93.39	269.74	177.37	275.	301.	275.	157.
300.00	99.60	269.74	177.37	300.	349415.26	300.	111150.87
325.00	105.81	269.74	177.37	325.	430443.56	325.	828144.10
350.00	112.02	269.74	177.37	350.	518955.38	350.	945485.95
375.00	118.23	269.74	177.37	375.	614808.89	375.	111150.87
400.00	124.44	269.74	177.37	400.	717898.36	400.	945485.95
425.00	130.65	269.74	177.37	425.	828144.10	425.	111150.87
450.00	136.86	269.74	177.37	450.	945485.95	450.	945485.95
475.00	143.07	269.74	177.37	475.	1062830.32	475.	111150.87
500.00	149.28	269.74	177.37	500.	1180214.79	500.	945485.95
525.00	155.49	269.74	177.37	525.	1297599.26	525.	111150.87
550.00	161.70	269.74	177.37	550.	1414983.73	550.	945485.95
575.00	167.91	269.74	177.37	575.	1532368.20	575.	111150.87
600.00	174.12	269.74	177.37	600.	1649752.67	600.	945485.95
625.00	180.33	269.74	177.37	625.	1767137.14	625.	111150.87
650.00	186.54	269.74	177.37	650.	1884521.61	650.	945485.95
675.00	192.75	269.74	177.37	675.	2001906.08	675.	111150.87
700.00	198.96	269.74	177.37	700.	2119290.55	700.	945485.95
725.00	205.17	269.74	177.37	725.	2236675.02	725.	111150.87
750.00	211.38	269.74	177.37	750.	2354059.49	750.	945485.95
775.00	217.59	269.74	177.37	775.	2471443.96	775.	111150.87
800.00	223.80	269.74	177.37	800.	2588828.43	800.	945485.95
825.00	230.01	269.74	177.37	825.	2706212.90	825.	111150.87
850.00	236.22	269.74	177.37	850.	2823597.37	850.	945485.95
875.00	242.43	269.74	177.37	875.	2940981.84	875.	111150.87
900.00	248.64	269.74	177.37	900.	3058366.31	900.	945485.95
925.00	254.85	269.74	177.37	925.	3175750.78	925.	111150.87
950.00	261.06	269.74	177.37	950.	3293135.25	950.	945485.95
975.00	267.27	269.74	177.37	975.	3410519.72	975.	111150.87
1000.00	273.48	269.74	177.37	1000.	3527904.19	1000.	945485.95

3. MAXIMUM STORAGE =

SI 704.42 54416:00

★ ★ ★ ★ ★ ★ ★ ★ ★ ★

HYDROGRAPH ROUTING

MINNISCEUNGO CREEK D/S HIGH TENSION WIRES

	ISTAQ	IComp	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
	21+00	1	0	0	0	0	0	0	0
				ROUTING DATA					
CLASS	C.GSS	AUG	IRGS	ISAME	IOPT	IPMP	LSTR		
C.C	0.000	0.00	1	1	0	0	0		
		NSTEL	LAG	AFSKK	X	TSK	STOPA	ISPRT	
	A3TPS	1	0	0.000	0.000	0.000	0.	0	

RECEIVED OCT 17 - CHANNEL ROUTING

GW(1)	GW(2)	GW(3)	ELNVT	ELVAX	RLNTH	SEL
.336	.9466	.0300	146.0	170.0	1900.	.01800

[illegible]

ST-REC	6.00	6.00	139.14	2.30	5.38	9.57	14.95	21.53	30.10	44.10	66.65
	52.33		139.14	129.09	247.91	312.14	380.72	453.65	530.93	612.56	698.54
CUTFLC	0.00	64.81	411.54	1217.35	2613.09	4737.85	7704.27	10314.66	13349.60	15349.60	25157.90
	4.325.55	61173.30	49736.98	198315.76	178784.95	238017.43	306177.81	383473.51	470136.95	566415.35	

257.
2887.

231
28553.

231
28553.

231
28553.

MAXIMUM STORAGE = 43.

MAXIMUM STAGE IS 131.6

STATION 39+00, PLAN 1, RTIO 2

OUTFLOW		STAGE	
9.	4.	7.	4.
11.	4.	7.	4.
5.	6.	10.	23.
59.	50.	44.	39.
76.	50.	44.	34.
42.	305.	426.	1543.
4733.	10041.	9896.	622.
5456.	3524.	3136.	7415.
1422.	1120.	2837.	2273.
509.	411.	947.	856.
213.	155.	331.	241.
72.	47.	112.	267.
		38.	100.
			34.
			27.

STOR

STAGE		STAGE	
9.	4.	7.	4.
11.	4.	7.	4.
5.	6.	10.	23.
59.	50.	44.	39.
76.	50.	44.	34.
42.	305.	426.	1543.
4733.	10041.	9896.	622.
5456.	3524.	3136.	7415.
1422.	1120.	2837.	2273.
509.	411.	947.	856.
213.	155.	331.	241.
72.	47.	112.	267.
		38.	100.
			34.
			27.

STAGE

STAGE		STAGE	
9.	4.	7.	4.
11.	4.	7.	4.
5.	6.	10.	23.
59.	50.	44.	39.
76.	50.	44.	34.
42.	305.	426.	1543.
4733.	10041.	9896.	622.
5456.	3524.	3136.	7415.
1422.	1120.	2837.	2273.
509.	411.	947.	856.
213.	155.	331.	241.
72.	47.	112.	267.
		38.	100.
			34.
			27.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
10041.	9236.	5123.	1945.	140702.
284.	267.	145.	55.	3984.
	4.91	10.89	12.41	12.47
	124.70	276.68	315.14	316.62
	4580.	10162.	11574.	11628.
	5649.	12534.	14276.	14343.

MAXIMUM STORAGE = 26.

MAXIMUM STAGE IS 127.5

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

PLAN 1 PLAN 2
 1.00 .50

STATION	AREA	PLAN 1	RATIO	PLAN 2
STATION 1	2.20	1	221.	441.
STATION 2	21.24	(261.12)	(170.56)
STATION 3	4.60	1	833.	416.
STATION 4	17.77	(236.05)	(118.02)
STATION 5	15.15	1	1740.	870.
STATION 6	23.11	(492.73)	(246.35)
STATION 7	15.10	1	1741.	873.
STATION 8	39.11	(493.17)	(247.20)
STATION 9	15.10	1	1745.	873.
STATION 10	39.11	(494.28)	(247.36)
STATION 11	15.10	1	1743.	872.
STATION 12	39.11	(495.35)	(247.15)
STATION 13	2.40	1	474.	237.
STATION 14	6.22	(134.24)	(67.12)
STATION 15	17.50	1	2019.	1009.
STATION 16	45.32	(569.71)	(284.84)
STATION 17	17.50	1	2002.	999.
STATION 18	45.32	(568.60)	(283.06)
STATION 19	17.50	1	2008.	1000.
STATION 20	45.32	(568.66)	(283.10)
STATION 21	17.50	1	2006.	1002.
STATION 22	45.32	(568.07)	(283.84)
STATION 23	17.50	1	2005.	1004.
STATION 24	45.32	(567.80)	(284.32)

PLAN 1 STATION 18+00

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
1.00	17416.	338.3	46.00
.50	8733.	336.0	46.00

PLAN 1 STATION 76+00

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
1.00	17416.	338.3	46.00
.50	8733.	336.0	46.00

1.00 17455. 279.3 46.00
.50 8735. 277.2 46.00

PLAN 1 STATION 114+0

RATIO	MAXIMUM FLOW, CFS	MAXIMUM		TIME HOURS
		STAGE, FT	STAGE, FT	
1.00	17493.	223.2	46.00	
.50	8728.	220.2	46.00	

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1		ELEVATION		INITIAL VALUE		SPILLWAY CPEST		TOP OF DAM	
RATIO OF PPE		MAXIMUM RESERVOIR W.S. ELEV		MAXIMUM STORAGE AC-FT		MAXIMUM OUTFLOW CFS		DURATION OVER TOP HOURS	
1.00		222.57		310.		20080.		21.00	
.50		215.74		255.		9996.		13.00	
		MAXIMUM DEPTH OVER DAM		MAXIMUM OUTFLOW CFS		DURATION OVER TOP HOURS		TIME OF MAX OUTFLOW HOURS	
		5.07						45.00	
		2.54						45.00	
								0.00	
								0.00	

PLAN 1 STATION 2+00

RATIO		MAXIMUM FLOW, CFS		MAXIMUM STAGE, FT		TIME HOURS	
1.00		20082.		184.6		45.00	
.50		10001.		184.0		45.00	

PLAN 1 STATION 21+00

RATIO		MAXIMUM FLOW, CFS		MAXIMUM STAGE, FT		TIME HOURS	
1.00		20061.		153.4		45.00	
.50		10024.		150.9		45.00	

PLAN 1 STATION 39+00

RATIO		MAXIMUM FLOW, CFS		MAXIMUM STAGE, FT		TIME HOURS	
1.00		20052.		131.6		45.00	
.50		10041.		127.5		45.00	

STABILITY ANALYSIS

APPENDIX E

TAMS

Job No. 1557-10

Project New York Dam Inspection GARNERVILLE

Subject Stability Analysis

Sheet 1 of 23

Date 6-2-80

By JJF

Ch'k. by _____

Assumptions

- 1) The unit weight of masonry is assumed to be 165 lbs/cuft
 - 2) Ice load of 5000 lbs/ft² acting about 1 ft from top of dam (COE Criteria)
 - 3) Angle of internal resistance of soil (fill) is assumed to be 35° based on observations and engineering judgment
 - 4) Dam Site is in Seismic Zone 2
 - 5) At rest E.P.P. Pressure for upstream Fill
- LOADING Conditions

CASE I - Normal loading; Lake level at top of crest El. 210. No Ice load.

CASE II - Normal loading; Lake level at top of crest El. 210. 5000 lbs/ft² Ice load.

CASE III - Unusual loading; Lake level at 1/2 P.M.F.

CASE IV - Extreme loading; Lake level at P.M.F.

CASE V - Unusual loading; Lake level at 1/2 P.M.F. crest and earthquake force of 0.05g.

TAMS

Job No. 1551
Project New York Dam Inspections - GARNERVILLE
Subject Stability Analysis

Sheet 2 of 23
Date 6-2-80
By JTF
Ch'k. by _____

Stability Criteria

- a) overturning - Resultant force shall fall within the middle third of the base for cases I and II and the resultant force shall fall within the middle half of base for cases III, IV, and V
- b) Sliding For case I+II, Friction factor of safety against sliding is to be 1.5 For case III, V Friction factor of safety against sliding is to be 1.25. For case IV friction factor of safety is to be 1.1

AD-A092 042

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/G 13/13
NATIONAL DAM SAFETY PROGRAM, GARNERVILLE DAM (INVENTORY NUMBER --E+C(U)
AUG 80 E O'BRIEN DACW51-79-C-0001

UNCLASSIFIED

NL

2 of 2
40 8
790012




END
DATE
FILMED
-B1
DTIC

TAMS

Job No. 1551-10
 Project NYS Dam Inspection
 Subject GARNERVILLE DAM - Stability Analysis
NON-OVER FLOW SECTION

Sheet 3 of 23
 Date 6-2-80
 By JTF
 Ch'k. by _____

Dead loads



Scale 1" = 10'

Σm about Toe

$w_1 = \frac{1}{2}(2.9)(6.45)(0.165) =$	15.43	\times	$\frac{MA.}{4.3}$	$=$	66.35
$w_2 = \frac{1}{2}(13)(2.9)(0.165) =$	62.2	\times	13.0	$=$	808.51
$w_3 = \frac{1}{2}(2.9)(6.45)(0.165) =$	15.43	\times	21.6	$=$	333.32
$w_4 = \frac{1}{2}(2.3)(4)(0.25) =$	5.75	\times	24.0	$=$	138.0
$\Sigma FY = 98.81$		$\Sigma MF = 1346.34$			

$$\bar{N} = \frac{1346.34}{98.81} = 13.63 - \text{OK within middle } 1/2$$

$$\bar{y} = 12.90 \text{ ft.}$$

TAMS

Job No. 1551-10

Project NYS Dam. Inspection

Subject GARNERVILLE DAM - Stability Analysis

Sheet 4 of 23


Date 6-2-80

By JJF

Ch'k. by _____

Hydrostatic Forces

a) - NORMAL LOADING



$\Sigma M_{TOE} =$

$$P = \frac{1}{2} \times 1.38 \times 22.1 =$$

$$\frac{K}{15.25} \times \frac{M.A.}{7.37} = \frac{KF}{112.39}$$

$$U = \frac{1}{2} \times 1.38 \times 25.9 =$$

$$\frac{17.87}{421.00} \times 17.27 = \frac{308.61}{421.00}$$

$$F_V \uparrow \quad 17.87$$

$$F_H \leftarrow \quad 15.25$$

$$M_o = \quad 421.00$$

TAMS

Job No. 1551-10

Project

NYS Dam Inspection

Subject

GARNERVILLE DAM - Stability Analysis


Sheet 5 of 13

Date 6-2-80

By JJF

Ch'k. by

EARTH Forces



Assumed ① Submerged
Unit weight

$$125.0 - 62.4 = 62.6 \text{ pcf}$$

$$- 0.0626$$

② At rest (K_0) with $\phi' = 25^\circ$

$$K_0 = 0.58$$

Scale 1" = 10'

$$EF = (0.6) \frac{1}{2} (45) (17.5) (0.0626) = \frac{K}{14.3}$$

$$\frac{MA}{7.5}$$

$$\frac{KF}{107.25}$$

ICE LOAD




$$\frac{K}{5.0} \times \frac{MA}{21.6} = \frac{KF}{100}$$

TAMS

Job No. 1551-10
 Project NYS Dam Inspection
 Subject GARNERVILLE DAM - Stability Analysis

Sheet 6 of 23
 Date 6-2-80
 By JJF
 Ch'k. by _____

1/2 PMF wselevation = 219.74



$$31.84 \times 0.0624 = 1.99$$

$$P_H = \frac{1.99 + 0.18}{2} (29) = 31.47 \leftarrow \times \quad \frac{MA}{10.47}$$

$$P_T = \frac{1}{2} (0.562) (9.0) (0.6) = 1.57 \rightarrow \times \quad 3.0$$

$$U = \frac{1.99 + 0.562 (25.9)}{2} = 33.05 \uparrow \times \quad 15.36$$

$$W_w = 0.0624 \left((5 \times 9.8) + \frac{9.8 \times 2.8 (1.5)}{2} \right) = 3.65 \times \quad 24.0$$

$$\leftarrow F_H = 29.95$$

$$\uparrow F_V = 29.4$$

$$M_O = 329.49 \quad M_R = 4.55$$

$$507.62$$

$$837.11 \quad 87.55$$

$$92.10$$

TAMS

Job No.: 1551-10

Project NYS Dam Inspection


Subject GARNERVILLE DAM - Stability Analysis

Sheet 7 of 23

Date 6-2-80

By JJA

Ch'k. by



$$P_H = \frac{2.18 + 0.37 \cdot (29)}{2}$$

$$P_T = \frac{1}{2} (0.22)(1/6)(0.6) =$$

$$u = \frac{2.18 + 0.72(2.59)}{2} =$$

$$W_w = \frac{5 \times 12.45 \times 0.1574 + 12.45 + 5 \times 1.5}{2} (0.624) = 4.75 \text{ k} \quad \checkmark \quad 24$$

K	m_1	m_0	m_2
37.01	11.07	409.1	

2.51 → 3.87 9.71

37.56↑ 1512 568.02

$$F_v = 32.81 \quad F_H = 34.5$$

	114.0
927.72	123.71

TAMS

Job No. 1551-10

Sheet 8 of 23

Project New York Dam Insp - GARNEVILLE

Date 6-2-80

Subject Stability ANALYSIS

By JJF

Ch'k. by _____

CASE I NORMAL LOADING - without Ice

	<u>F_V</u>	<u>F_H</u>	<u>M_R</u>	<u>M_O</u>
Dead LOAD	98.81	0	1346.34	
Hydrostatic	-17.87	15.25		421.0
EARTH FORCE		14.3		107.5
	<u>80.94</u>	<u>29.55</u>	<u>1346.34</u>	<u>528.25</u>

$$\Sigma m = 1346.34 - 528.25 = 817.84$$

$$\bar{e} = \frac{25.9}{2} - \frac{817.84}{80.94}$$

$$\bar{e} = 12.95 - 10.10 = 2.85 \quad \text{OK inside middle } \frac{1}{3}$$

$$P = \frac{80.94}{25.9} \left(1 \pm \frac{6 \times 2.85}{25.9} \right) \frac{1000}{144} = 21.7 \pm 14.3 \left. \begin{array}{l} 36.0 \\ 7.4 \end{array} \right\}$$

Friction Factor of Safety

$$\text{FFS} \quad \frac{80.94 \times \tan 35^\circ}{29.55} = 1.92 \quad \text{OK}$$

TAMS

Job No. 1551

Sheet 9 of 13

Project New York Dam Insp. - GARNERVILLE

Date 6-2-80

Subject Stability Analysis

By JTF

Ch'k. by _____

CASE II NORMAL LOADING WITH ICE LOAD

	<u>FV</u>	<u>FH</u>	<u>M_v</u>	<u>M_h</u>
DEAD LOAD	98.81	0	1346.34	—
Hydrostatic	-17.87	15.75	—	421.0
EARTH FORCE	0	14.30	0	107.25
ICE LOAD	0	5.0	0	108.00
	<u>80.94</u>	<u>34.55</u>	<u>1346.34</u>	<u>636.25</u>

$$\Sigma m = 1346.34 - 636.25 = 710.09$$

$$\bar{e} = \frac{25.9}{2} - \frac{710.09}{80.94}$$

$$\bar{e} = 12.95 - 8.77 = 4.18'$$

Resultant location $8.77 - 8.6 = 0.17'$ OK within the middle 1/3 of base

$$\bar{p} = \frac{80.94}{25.9} \left(1 \pm \frac{6 \times 4.18}{25.9} \right) \times \frac{1000}{144} = 21.7 \pm 21.0 \quad \begin{matrix} 42.7 \text{ Tc} \\ 0.7 \text{ heel} \end{matrix}$$

FRICTION FACTOR OF SAFETY

$$FFS = \frac{80.94 \times \tan 35^\circ}{34.55} = 1.64 \quad \underline{\text{OK}}$$

TAMS

Job No. 155-10

Sheet 10 of 13

Project NYS Dam Insp. GARNERVILLE

Date 6-7-80

Subject Stability Analysis

By JJF OR

Ch'k. by _____

Case III - $\frac{1}{2}$ PMF

	$\frac{FV}{}$	$\frac{FH}{}$	$\frac{MR}{}$	$\frac{Mo}{}$
Dead Load	98.81	0	1346.34	
Hydrostatic	30.67	31.63	104.39	888.83
Earth Force	0	14.3	0.	107.25
	<u>68.14</u>	<u>45.93</u>	<u>1450.73</u>	<u>996.08</u>

$$\Sigma M = 1450.73 - 996.08 = 454.65$$

$$\bar{e} = \frac{25.9}{2} - \frac{454.65}{68.14} = 6.28$$

$$\frac{454.65}{68.14} - \frac{25.9}{4} = -$$

$$6.67 - 6.48 = 0.19 \quad - \text{inside middle } \frac{1}{2} \text{ of base}$$

$$\bar{p} = \frac{68.14}{25.9} \left(1 \pm \frac{6 \times 6.28}{25.9} \right) \frac{1000}{144} = 18.27 \pm 26.49$$

ToC 44.76
Hed - 8.22

Friction factor of safety

$$FFS = \frac{68.14 \tan 35^\circ}{45.93} = 1.03 < 1.25$$

\therefore No Good

TAMS

Job No. 1551-10

Project NYS Dam Inspection - Garnerville

Subject Stability Analysis

Sheet 11 of 23

Date 6-2-80

By JTF

Ch'k. by _____

Case IV PMF

	<u>FV</u>	<u>EH</u>	<u>MR</u>	<u>Mo</u>
Dead Load	98.81		1346.31	
Hydrostatic	-32.81	34.50	123.71	977.72
Earth Force		14.3		107.25
	<u>66.0</u>	<u>48.8</u>	<u>1470.05</u>	<u>1084.96</u>

$$EM = 1470.05 - 1084.96 = 385.09$$

$$\bar{e} = \frac{25.9}{2} \frac{385.09}{66.0} = 6.62 \quad - \quad \text{No good outside middle } 1/2$$

$$\frac{385.09}{66} - \frac{25.9}{4} = -0.39$$

$$\bar{p} = \frac{66.0}{25.9} \left(1 \pm \frac{6 \times 6.62}{25.9} \right) \frac{1000}{144} = 17.69 \pm 27.13$$

$$\therefore 44.82 (\text{toe})$$

$$-9.44 (\text{heel})$$

Friction Factor of Safety

$$FFS = \frac{66.0 \tan 35^\circ}{48.8} = 0.95 < 1.15 \quad \text{No good}$$

TAMS

Job No. 155170
 Project NYS DAM Insp WATERVILLE
 Subject Stability Analysis


Sheet 12 of 23
 Date 6-2-80
 By JTF
 Ch'k. by _____

CASE II ; NORMAL LOADING

Zone 2 = 0.05

ZANCERS Method

$C = 0.64$
 when $\alpha = 12.5$



① Hydrodynamic Forces

$$P = 0.64 \times 0.05 \times 0.0624 \times (22.1)^2 = 0.98$$

$$M_p = (0.98) (0.4) \times 22.1 = 8.7 \text{ Kf}$$

② Dynamic Force

a) $W_F = 14.1 \text{ K} \times 0.64 \times 0.05 = .46$

$$M_p = 0.46 \times 7.5 = 3.4 \text{ K}$$

b) $W_D = 0.05 (98.81) = 4.94$

$$M_{WD} = 4.94 \text{ K} \times 12.90 = 63.73 \text{ Kf}$$

	Fv	Fh	MR	Mo
Dead Load	98.81	0	1346.34	
Hydrostatic	-17.87	15.25		421.0
EMITTANCE		14.3		107.25
Hydrodynamic		0.98		8.1
DYNAMIC		5.4		67.13
	80.94	35.93	1346.34	604.08

$$EM = 1346.34 - 604.08 = 742.26$$

$$\frac{742.26}{80.94} = 9.17$$

$$\bar{e} = \frac{25.9}{2} - 9.17$$

$$= 3.78$$

OK within
 middle 1/2
 OK center
 1/2

TAMS

Job No. 1551-10

Project NYS Dam Insp - GARNEVILLE

Subject Stability Analysis

Sheet 13 of 23

Date 6-2-80

By Joel

Ch'k. by _____

Case II cont.

$$p = \frac{80.94}{25.9} \cdot \left(1 \pm \frac{6 \times 3.78}{25.9}\right) \times \frac{1000}{144} = 21.7 \pm 19 \left. \begin{array}{l} 40 \text{ psi} \\ 2.7 \text{ psi} \end{array} \right\}$$

FRICTION FACTOR OF SAFETY

$$FFS = \frac{80.94 \times \tan 35^\circ}{35.93} = 1.51 \text{ OK}$$

TAMS

Job No. 1546-10

Project NYS State Dam Insp - GARNERVILLE

Subject Stability - Spillway Section


Sheet 14 of 23

Date 6-11-80

By JJF

Ch'k. by _____

Dead loads - Case 2



Scale 1" = 10'

ΣM about Toe

	K	MK	KF
$w_1 = \frac{1}{2}(4.92)(22.1)(0.165) =$	8.97	3.28	29.42
$w_2 = 16.06(22.1)(0.165) =$	58.56	12.95	758.33
$w_3 = \frac{1}{2}(4.92)(22.1)(0.165) =$	8.97	22.62	202.91
$w_4 = \frac{1}{2}(2.3)(4)(0.125) =$	5.75	24.0	138.0
	<u>82.25</u>		<u>1128.71</u>

$$\bar{X} = \frac{1128.71}{82.25} = 13.72'$$



$$\bar{Y} = 11.9'$$

TAMS

Job No. 1546-10
 Project NYS State Dam Insp - GARNERVILLE
 Subject Stability - Spillway Section

Sheet 15 of 3
 Date 6-11-80
 By JJF
 Ch'k. by _____

Hydrostatic Forces Normal Acting - Case 2



Backfill

7.37

Scale 1" = 10'

$$0.0624 \times 22.1 = 1.38 \text{ K/ft}$$

EM TOR

	K	ft	K/ft
$P = \frac{1}{2} \times 1.38 \times 22.1 =$	15.25	7.37	112.39

$W = \frac{1}{2} \times 1.38 \times 25.9 =$	17.87	17.27	308.61
---	-------	-------	--------

421.0

$$F_v = \uparrow 17.37 \text{ K}$$

$$F_H = \leftarrow 15.25 \text{ K}$$


$$M = 421.00 \text{ K/ft}$$

TAMS

Job No. 1546-10
 Project NYS State Dam Insp - GARNERVILLE
 Subject Stability - Spillway Section

Sheet 16 of 23
 Date 6-11-80
 By JJF
 Ch'k. by _____

EARTH Forces - Case - 2



Assumed
 ① Saturated Unit Weight
 $125.0 - 62.4 = 62.6$ pcf
 ② At Rest K_0 with $\phi = 25^\circ$
 $K_0 = 0.58$

Scale 1" = 10'

$$EF = 0.58 \left(\frac{1}{2} \right) (45) (17.5) (0.0626) \quad \begin{matrix} K \\ 17.5 \end{matrix} \quad \begin{matrix} EF \\ 107.25 \end{matrix} \quad \begin{matrix} KE \\ 107.25 \end{matrix}$$

ICE LOAD

$$\frac{K}{5.0} = \frac{17.4}{21.6} = \frac{KE}{108.0}$$

TAMS

Job No. 1546-10

Project NYS State Dam Insp - GARNERVILLE


Subject Stability - Spillway section

Sheet 17 of 23

Date 6-11-80

By JTF

Ch'k. by _____



TAMS

Job No. 1546-10

Project NYS State Dam Insp - GARNERVILLE

Subject Stability - Spillway Section


Sheet 18 of 23

Date 6-11-80

By JTF

Ch'k. by _____


PMF W.S. ELEV 222.87 (159.7)



$$0.0624 \times 11.6 = 0.72$$

$$34.97 \times 0.0624$$

$$= 2.18$$



$$P_H = \frac{2.18 + 0.80 \cdot (22.1)}{2} = 32.93 \leftarrow \begin{matrix} k & M_A & M_B & M_R \\ & 8.8 & 281.8 & \end{matrix}$$

$$P = \frac{1}{2} (0.72) (11.6 \times 0.6) = 2.51 \rightarrow 3.87 \quad 9.7$$

$$u = \frac{2.18 + 0.72 (25.9)}{2} = 37.56 \uparrow \quad 15.12 \quad 568.02$$

$$W = \frac{5 \times 12.45 \times 0.0624 + (0.0624) (12.45 + 5.97) (1.5)}{2} = 4.75 \downarrow \quad 24.0 \quad 114.0$$

$$F_H = 39.42$$

$$F_V = 33.81$$

$$257.82 \quad 123.7$$

TAMS

Job No. 1546-10

Sheet 19 of 23

Project NY'S DAM Insp - GARNERVILLE

Date 6-11

Subject Stability Spillway Section

By JJF

Ch'k. by _____

Case I Normal Loading - Without Ice

	<u>FV</u>	<u>FH</u>	<u>MR</u>	<u>Mo</u>
Dead Load	82.25		1128.71	
Hydrostatic	-17.87	15.25		421.0
EARTH FORCE		14.3		107.25
	<u>64.38</u>	<u>29.55</u>	<u>1128.71</u>	<u>528.25</u>

$$\Sigma M = 1128.71 - 528.25 = 600.26$$

$$\bar{e} = \frac{25.9}{2} - \frac{600.26}{64.38} = 12.95 - 9.32 = 3.62'$$

Resultant location

$$9.32 - 8.6 = 0.72 \quad - \text{OK INSIDE M.O.I. } 1/3$$

$$\bar{p} = \frac{64.38}{25.9} \left(1 \pm \frac{6 \times 3.2}{25.9} \right) \frac{1000}{144} = 17.26 \pm 12.80 = \left. \begin{array}{l} 30.05 \text{ psf} \\ 4.46 \text{ psf} \end{array} \right\}$$

Friction Factor of Safety

$$\frac{64.38 \tan 35^\circ}{29.55} = 1.53$$

TAMS

Job No. 1546-10

Sheet 120 of 23

Project NYS Dam Insp GARNERVILLE

Date 6-11-50

Subject Stability - Spillway Section

By JTF

Ch'k. by _____

Case II Normal Loading - With Ice load

	$\frac{F_v}{}$	$\frac{F_H}{}$	$\frac{M_e}{}$	$\frac{M_o}{}$
Dead Load	8225		1128.71	
Hydrostatic	-17.87	15.25		421.0
Earth Force		14.3		107.25
Ice load	0	5.0	0	108.1
	<u>64.38</u>	<u>34.55</u>	<u>1128.71</u>	<u>636.25</u>

$$\Sigma M = 1128.71 - 636.25 = 492.46$$

$$\bar{e} = \frac{25.9}{2} - \frac{492.46}{64.38} = 7.65'$$

$$\text{Resultant Location} = \frac{492.46}{64.38} - \frac{25.9}{3} = -0.95' \quad \text{No good ends made}$$

$$\bar{p} = \frac{64.38}{25.9} \left(1 + \frac{6 \times 7.65}{25.9} \right) \frac{1000}{1111} = 21.7 \pm 38.45 \left\{ \begin{array}{l} 60.15 \\ -16.99 \end{array} \right.$$

Friction Factor of Safety

$$\frac{64.38 \tan 35^\circ}{34.55} = 1.30$$

Not acceptable

TAMS

Job No. 1546-10

Sheet 21 of 23

Project NYS Dam Inspection - GARNERVILLE

Date 6-11

Subject Stability Spillway Section

By JTF

Ch'k. by _____

Case III - $\frac{1}{2}$ P.M.F.

	<u>FV</u>	<u>FH</u>	<u>MR</u>	<u>Mo</u>
Dead load	82.25		1128.71	
Hydrostatic	-29.4	27.21	92.10	769.1
EARTH FORCE		14.3		107.25
	<u>52.85</u>	<u>41.51</u>	<u>1220.8</u>	<u>876.35</u>

$$E.M. = 1220.8 - 876.35 = 344.46 \text{ LF}$$

$$\frac{25.9}{2} - \frac{344.46}{52.85} = 6.79'$$

$$\frac{344.46}{52.85} - \frac{25.9}{4} = 0.29$$

$$\bar{p} = \frac{52.85}{25.9} \left(\frac{1 \pm 6 \times 5.93}{25.9} \right) \frac{1000}{144} =$$

Marginalley in
Center $\frac{1}{2}$
14.17 \pm 19.5 } 33.67 psi
-533 psi

Friction Factor of Safety

$$\frac{52.85 \tan 35^\circ}{41.51} = 0.90 < 1.25 \text{ No Good}$$

TAMS

Job No. 1564-10

Sheet 22 of 23

Project NYS Dam Insp. GARNEVILLE

Date 6-11

Subject Stability - Spillway

By JTF

Ch'k. by _____

Case IV PMF

	<u>FV</u>	<u>FH</u>	<u>MR</u>	<u>Mo</u>
Dead Load	82.25		1128.71	
Hydrostatic	-52.81	30.42	123.70	857.82
Earth Force		14.3		107.25
	<u>49.44</u>	<u>44.72</u>	<u>1252.41</u>	<u>965.07</u>

$$\Sigma M = 1252.41 - 965.07 = 287.35$$

$$\bar{e} = \frac{287.34 - \frac{25.9}{4}}{49.44} = 0.42$$

No good outside middle 1/2

$$\bar{p} = \frac{49.44}{25.9} \left(1 \pm \frac{6 \times 6.63}{25.9} \right) \left(\frac{1000}{144} \right) = 13.25 \pm 2.28$$

33.58 psi (top)
- 7.03 psi (bottom)

Friction Factor of Safety

$$FFS = \frac{49.44 \tan 30^\circ}{44.72} = 0.78 < 1.00 \text{ No good}$$

TAMS

Job No. 1546
 Project NYS Dam Inspection - GARNEVILLE
 Subject Stability Analysis - Spillway

Sheet 23 of 23
 Date 6-11
 By JJF
 Ch'k. by _____

Case II - Normal loading

Hydrodynamic Force =
 Dynamic Force - BIRTH
 - Dead
 $0.05(82.25) \times 11.9$

8.7 KF (see Sh. 12)
 3.4 KF
48.93 KF
 61.03

	<u>FV</u>	<u>FH</u>	<u>MR</u>	<u>MO</u>
Dead Load	82.25		1128.71	
Hydrostatic	- 17.87	15.25		421.0
EARTH Force		14.3		107.25
Hydrodynamic		0.98		8.7
Dynamic		4.58		52.33
	<u>64.38</u>	<u>35.11</u>	<u>1128.71</u>	<u>589.28</u>

$$EM = 1128.71 - 589.28 = 539.43$$

$$\frac{25.9}{2} - \frac{539.43}{64.38} = 4.57$$

$$\frac{539.43}{64.38} = 8.37$$

$$- 6.47$$

$$\hline 1.89$$

OK - inside middle 1/2

$$\bar{P} = \frac{64.38}{25.9} \left(1 \pm \frac{6 \times 4.57}{25.9} \right) \frac{1000}{144} = 17.26 \pm 18.27 \left. \begin{array}{l} 35.53 \text{ pr} \\ -1.01 \text{ pr} \end{array} \right\}$$

Friction Factor

$$\frac{64.38 \tan 35^\circ}{35.11} = 1.28 \quad \text{OK}$$

REFERENCES

APPENDIX F

References

1. "HEC-1 Flood Hydrograph Package for Dam Safety Investigations", U.S. Army Corps of Engineers, September 1978
2. "Lower Hudson River Basin Hydrolic Flood Routing Model" for New York District Corps of Engineers, Water Resources Engineers, Inc., January 1977
3. "Standard Project Flood Determination", EM-1110-2-1411, Army Corps of Engineers, Washington, D.C., Rev. 1965
4. "Probable Maximum Precipitation Estimates, United States East of the 105th Meridian", Hydrometeorological Report No. 51, National Weather Service, June 1978
5. "National Program of Inspection of Dams", Vol. 3, Department of the Army, Office of the Chief of Engineers, 1975
6. "Flood Hydrograph Analyses and Computations", EM-1110-2-1405, U.S. Army Corps of Engineers, August, 1959
7. "Recommended Guidelines for Safety Inspection of Dams", Department of the Army, Office of the Chief of Engineers, Appendix D
8. "The Geology of New York State", by Broughton, J.E., et al., N.Y. State Museum and Science Service, Geological Survey, Albany, New York, Map and Chart Series: No. 5, 1962
9. "Soil Association Map of New York State", by M.G. Cline, New York State College of Agriculture, Cornell University, Ithaca, New York, February, 1963
10. "Orange County Soils. Soil Association Leaflet 2", by E.G. Knox, et al., New York State College of Agriculture, Cornell University, Ithaca, New York, October, 1954